

TPS Status Report



TPS Number: TP-0649-12

TP Program #: 60-0649-12

Version: 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------------|-------------|-------|-------------|------|------|------------|-----|----------|
| GE | 735SUE Autothrottle | 9/2/2011 | ATA | 22-30-10 | V1 | 6 | 11/29/2010 | | |
| GE | 735SUE Autothrottle | 9/2/2011 | ATLAS | 22-30-10 | PP1- | 2 | 12/30/2011 | | |
| GE | 735SUE Autothrottle | 9/2/2011 | ATA | 22-30-13 | V1 | 8 | 3/2/2010 | | |
| GE | 735SUE Autothrottle | 9/2/2011 | ATLAS | SSP13174- | | 4 | 12/30/2011 | | |
| GE | 735SUE Autothrottle | 9/2/2011 | ATLAS | SSP19952- | | 4 | 11/19/1999 | | |

TPS Number: TP-0649-13

TP Program #: 60-0649-13

Version: 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| GE | 755SUE Autothrottle | 7/1/2010 | ATLAS | 22-30-11 | PP1- | 0 | 12/7/1992 | | |
| GE | 755SUE Autothrottle | 7/1/2010 | ATA | 22-30-11 | V1 | 7 | 2/28/2010 | | |

TPS Number: TP-0649-16

TP Program #: 60-0649-16

Version: 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|----------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | HF9031 HF Comm | 10/28/1999 | MISC | NO ATA | .0777 | 2 | 6/1/1996 | | |

TPS Number: TP-0649-17

TP Program #: 60-0649-17

Version: 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | ADF-462 ADF Rcvr | 7/29/1999 | ATA | 34-53-40 | .0773 | 3 | 12/8/1995 | | |

TPS Status Report



TPS Number: TP-0649-18

TP Program #: 60-0649-18 **Version:** 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|----------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | TDR-94D Mode-S | 1/25/2000 | ATA | 34-50-96 | .0778 | | 7/1/1998 | | |

TPS Number: TP-0649-19

TP Program #: 60-0649-19 **Version:** 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|-------------|------|------|-----------|-------|----------|
| Honeywell | RNA-34AF VOR | 1/29/2001 | ATA | 34-55-01 | 134A | 3 | 2/1/1988 | 34-17 | 1/1/1996 |

TPS Number: TP-0649-20

TP Program #: 60-0649-20 **Version:** 1.5

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-------------|-------------|-------|-------------|------|------|------------|--------|-----------|
| Honeywell | DMA-37A DME | 8/1/2007 | ATA | 34-51-33 | 137A | 8 | 11/19/2012 | 34-111 | 6/22/2006 |
| Honeywell | DMA-37A DME | 8/1/2007 | ATA | 34-51-34 | 37A | 6 | 12/15/2004 | 34-41 | 5/7/2007 |

TPS Number: TP-0649-22

TP Program #: 60-0649-22 **Version:** 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------------|-------------|-------|----------------|------|------|-----------|-----|----------|
| Honeywell | KTR909B UHF Comm | 1/18/2000 | MISC | 924-01370-0000 | | 7 | 2/2/1999 | | |

TPS Status Report



TPS Number: TP-0649-23

TP Program #: 60-0649-23 **Version:** 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Teledyne | 2233000 DFDAU | 12/13/1999 | ATA | 31-32-80 | | 3 | 6/1/1997 | | |

TPS Number: TP-0649-25

TP Program #: 60-0649-25 **Version:** 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|---------------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | Cabin Pressure Controller | 8/6/2007 | ATA | 21-31-48 | 4060 | 12 | 11/9/2007 | | |

TPS Number: TP-0649-26

TP Program #: 60-0649-26 **Version:** 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|----------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | DG1035AB03 DAA | 8/28/2007 | ATA | 34-21-16 | 352- | 3 | 6/1/2006 | | |

TPS Number: TP-0649-27

TP Program #: 60-0649-27 **Version:** 1.10

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-------------|-------------|-------|----------------|------|------|-----------|-----|----------|
| Honeywell | RIA-35B ILS | 12/30/1999 | TRD | 004-50304-0001 | | A | 3/4/1996 | | |

TPS Status Report



TPS Number: TP-0649-28

TP Program #: 60-0649-28 **Version:** 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-------------|-------------|-------|-------------|------|------|-----------|-------|------------|
| Honeywell | RVA-36B VOR | 1/8/2008 | TRD | 004-50327 | | C | 1/25/1996 | | |
| Honeywell | RVA-36B VOR | 1/8/2008 | ATA | 34-55-33 | .36A | 3 | 8/15/2004 | 34-25 | 11/30/2005 |
| Honeywell | RVA-36B VOR | 1/8/2008 | ATA | 34-55-34 | .36A | 3 | 8/15/2004 | 34-28 | 11/30/2005 |

TPS Number: TP-0649-29

TP Program #: 60-0649-29 **Version:** 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | DFA-75B ADF Rcvr | 8/5/2009 | TRD | 004-50366 | | E | 9/23/2006 | | |

TPS Number: TP-0649-30

TP Program #: 60-0649-30 **Version:** 1.9

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | RTA-44D VHF Comm | 4/8/2013 | TRD | 004-50336 | | J | | | |

TPS Number: TP-0649-31

TP Program #: 60-0649-31 **Version:** 2.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | RTA-83A VHF Comm | 3/12/2007 | ATA | 23-20-39 | 183C | 1 | 11/1/2005 | | |

TPS Status Report



TPS Number: TP-0649-35

TP Program #: 60-0649-35

Version: 3.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|---------------|-------|------|-----------|-----|----------|
| Honeywell | TPA-81A TCAS | 12/12/2011 | TELI | 00450018-0049 | | 7L | | | |
| Honeywell | TPA-81A TCAS | 12/12/2011 | ATA | 34-45-45 | .81A | 3 | 3/5/2013 | | |
| Honeywell | TPA-81A TCAS | 12/12/2011 | MISC | TPT-81A-34-6 | I-36C | 39 | 5/30/2012 | | |

TPS Number: TP-0649-36

TP Program #: 60-0649-36

Version: 2.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------------|-------------|-------|--------------|-------|------|-----------|-----|----------|
| Honeywell | TRA-67A ATC/Mode-S | 5/6/2015 | ATA | 34-54-36 | .67A | 9 | 1/4/2013 | | |
| Honeywell | TRA-67A ATC/Mode-S | 5/6/2015 | TELI | 8070178-0040 | | 4M | | | |
| Honeywell | TRA-67A ATC/Mode-S | 5/6/2015 | MISC | TRT-67A-34-3 | I-359 | 24 | 12/8/2011 | | |

TPS Number: TP-0649-37

TP Program #: 60-0649-37

Version: 2.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| GE | 2577B/D/F CDU | 6/14/2010 | ATLAS | 34-61-03 | 1A | 8 | 4/25/2003 | | |
| GE | 2577B/D/F CDU | 6/14/2010 | ATA | 34-61-03 | 1 | 21 | 3/30/2012 | | |
| GE | 2577B/D/F CDU | 6/14/2010 | ATA | 34-61-08 | 1 | 18 | 4/20/2012 | | |
| GE | 2577B/D/F CDU | 6/14/2010 | ATLAS | 34-61-08 | 1A | 6 | 4/25/2003 | | |
| GE | 2577B/D/F CDU | 6/14/2010 | ATA | 34-61-11 | 1 | 13 | 4/6/2012 | | |
| GE | 2577B/D/F CDU | 6/14/2010 | ATLAS | 34-61-11 | 1A | 8 | 4/25/2003 | | |

TPS Status Report



TPS Number: TP-0649-38

TP Program #: 60-0649-38 **Version:** 1.8

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Collins | ADF-700 ADF Rcvr | 11/18/2009 | ATA | 34-53-70 | 0771 | 25 | 5/23/2011 | | |
| Collins | ADF-700 ADF Rcvr | 11/18/2009 | ATA | 34-53-77 | 0775 | 22 | 8/4/2011 | | |

TPS Number: TP-0649-39

TP Program #: 60-0649-39 **Version:** 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Collins | EDU-766D/776D EDU | 2/6/2018 | ATA | 34-22-60 | 0774 | 14 | 1/10/2011 | | |

TPS Number: TP-0649-41

TP Program #: 60-0649-41 **Version:** 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|----------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Boeing | Audio Accessory Unit | 9/28/1999 | ATA | 23-42-61 | | | 3/1/1999 | | |

TPS Number: TP-0649-42

TP Program #: 60-0649-42 **Version:** 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Thales | ERT-530A Radio Alt | 2/4/2011 | ATA | 34-42-35 | | 12 | 9/15/2010 | | |

TPS Status Report



TPS Number: TP-0649-43

TP Program #: 60-0649-43 **Version:** 2.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Thales | TLS-755 MMR | 12/10/2010 | ATA | 34-36-31B | | 6 | 3/31/2009 | | |

TPS Number: TP-0649-44

TP Program #: 60-0649-44 **Version:** 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | DME-900 DME | 3/26/2012 | ATA | 34-52-94 | .081C | 16 | 5/6/2013 | | |

TPS Number: TP-0649-45

TP Program #: 60-0649-45 **Version:** 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------|-------------|-------|-------------|-------|------|------------|-----|----------|
| Collins | VHF-900/900B Comm | 5/22/2012 | ATA | 23-12-90 | .077C | 45 | 10/28/2013 | | |

TPS Number: TP-0649-46

TP Program #: 60-0649-46 **Version:** 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------------|-------------|-------|-------------|------|------|-----------|--------|------------|
| Honeywell | RIA-35A ILS Rcvr | 9/17/2007 | ATA | 34-36-31 | | 12 | 9/1/2002 | 34-167 | 11/29/2006 |
| Honeywell | RIA-35A ILS Rcvr | 9/17/2007 | ATA | 34-36-32 | .35A | 6 | 9/1/2002 | 34-142 | 12/7/2006 |

TPS Status Report



TPS Number: TP-0649-47

TP Program #: 60-0649-47

Version: 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|----------------|-------------|-------|-------------|------|------|-----------|--------|------------|
| Honeywell | RVA-36A VOR/MB | 9/17/2007 | ATA | 34-55-31 | 136A | 12 | 9/1/2002 | 34-137 | 11/29/2006 |
| Honeywell | RVA-36A VOR/MB | 9/17/2007 | ATA | 34-55-32 | 36A | 5 | 9/1/2002 | 34-86 | 11/30/2006 |

TPS Number: TP-0649-48

TP Program #: 60-0649-48

Version: 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------|-------------|-------|-------------|------|------|-----------|-----|----------|
| GE | 2904 FMC | 9/5/2008 | ATLAS | 34-61-01 | 1A | 05 | 9/19/2003 | | |
| GE | 2904 FMC | 9/5/2008 | ATA | 34-61-01 | 1 | 11 | 8/6/2004 | | |
| GE | 2904 FMC | 9/5/2008 | ATLAS | 34-61-06 | 1A | 08 | 9/20/2002 | | |
| GE | 2904 FMC | 9/5/2008 | ATA | 34-61-06 | 1 | 14 | 7/11/2003 | | |
| GE | 2904 FMC | 9/5/2008 | ATLAS | 34-61-10 | 1A | 07 | 2/1/2002 | | |
| GE | 2904 FMC | 9/5/2008 | ATA | 34-61-10 | 1 | 08 | 2/1/2012 | | |

TPS Number: TP-0649-49

TP Program #: 60-0649-49

Version: 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Collins | MCDP-701 MCDP | 12/4/2000 | ATA | 22-41-70 | 077C | 17 | 4/5/2005 | | |
| Collins | MCDP-701 MCDP | 12/4/2000 | ADATE | 826-8426 | | -003 | | | |

TPS Status Report



TPS Number: TP-0649-50

TP Program #: 60-0649-50

Version: 2.7

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | TTR-920 TCAS | 9/2/2014 | MPS | 04-7021-06 | | 3.3 | | | |
| Collins | TTR-920 TCAS | 9/2/2014 | ATA | 34-40-86 | .0776 | 30 | 7/7/2014 | | |
| Collins | TTR-920 TCAS | 9/2/2014 | ATA | 34-40-90 | .0777 | 9 | 7/7/2014 | | |
| Collins | TTR-920 TCAS | 9/2/2014 | ADATE | 826-7021 | | -034 | | | |

TPS Number: TP-0649-51

TP Program #: 60-0649-51

Version: 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | MCP-701 MCP | 3/28/2001 | ATA | 22-11-71 | .0817 | 3 | 7/6/2010 | | |
| Collins | MCP-701 MCP | 3/28/2001 | ADATE | 826-5339 | | -005 | | | |

TPS Number: TP-0649-52

TP Program #: 60-0649-52

Version: 1.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------------|-------------|-------|-------------|------|------|-----------|--------|-----------|
| Honeywell | RTA-44A VHF Comm | 5/20/2006 | ATA | 23-12-34 | .44A | 3 | 4/1/2003 | 23-143 | 9/25/2004 |
| Honeywell | RTA-44A VHF Comm | 5/20/2006 | ATA | 23-20-33 | 144/ | 13 | 9/1/2002 | 23-128 | 9/30/2007 |

TPS Status Report



TPS Number: TP-0649-55

TP Program #: 60-0649-55

Version: 1.30

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Collins | VOR-700/A VOR | 11/7/2003 | ATA | 34-55-70 | | 19 | 3/22/2010 | | |
| Collins | VOR-700/A VOR | 11/7/2003 | ATA | 34-55-72 | | 17 | 2/6/2009 | | |

TPS Number: TP-0649-56

TP Program #: 60-0649-56

Version: 1.7

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------|-------------|-------|-------------|-------|------|------------|-----|-----------|
| Collins | ILS-700/A ILS | 10/28/2008 | ATA | 34-36-70 | .0770 | 5 | 11/16/1998 | 41 | 8/3/2011 |
| Collins | ILS-700/A ILS | 10/28/2008 | ATA | 34-36-72 | .0775 | 4 | 11/23/1998 | 34 | 12/5/2008 |

TPS Number: TP-0649-57

TP Program #: 60-0649-57

Version: 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | ILS-720 ILS | 8/17/2010 | ATA | 34-36-76 | .0775 | 8 | 10/1/2010 | | |

TPS Number: TP-0649-58

TP Program #: 60-0649-58

Version: 1.7

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | VHF-700/A VHF Comm | 10/21/2009 | ATA | 23-12-70 | .0771 | 9 | 7/1/1999 | 55 | 9/9/2010 |
| Collins | VHF-700/A VHF Comm | 10/21/2009 | ATA | 23-12-74 | .0773 | 5 | 10/1/1998 | 49 | 5/1/2012 |
| Collins | VHF-700/A VHF Comm | 10/21/2009 | ATA | 23-12-76 | .0775 | 4 | 7/1/1999 | 49 | 5/3/2012 |

TPS Status Report



TPS Number: TP-0649-59

TP Program #: 60-0649-59 **Version:** 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------|-------------|-------|-------------|-------|------|-----------|-----|-----------|
| Collins | VHF-700B VHF Comm | 1/20/2010 | ATA | 23-12-79 | .0778 | 1 | 4/1/1998 | 42 | 2/15/2011 |

TPS Number: TP-0649-60

TP Program #: 60-0649-60 **Version:** 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------------|-------------|-------|-------------|------|------|-----------|--------|-----------|
| Honeywell | DFA-75A ADF Rcvr | 10/4/2012 | ATA | 34-53-31 | 175A | 10 | 9/1/2002 | 34-149 | 12/5/2006 |
| Honeywell | DFA-75A ADF Rcvr | 10/4/2012 | ATA | 34-53-32 | .75A | 3 | 9/1/2002 | 34-94 | 2/2/2004 |

TPS Number: TP-0649-61

TP Program #: 60-0649-61 **Version:** 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | DME-700 DME | 11/11/2009 | ATA | 34-52-70 | .0771 | 25 | 8/11/2010 | | |
| Collins | DME-700 DME | 11/11/2009 | ATA | 34-52-72 | .0775 | 18 | 2/5/2014 | | |

TPS Number: TP-0649-62

TP Program #: 60-0649-62 **Version:** 1.20

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|------------|-----|-----------|
| Collins | FCC-702 FCC | 12/29/2003 | ATA | 22-11-82 | .0774 | 4 | 12/15/1996 | 48 | 10/2/2001 |
| Collins | FCC-702 FCC | 12/29/2003 | ADATE | 826-9165 | | -007 | | | |

TPS Status Report



TPS Number: TP-0649-63

TP Program #: 60-0649-63 **Version:** 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------------|-------------|-------|-------------|------|------|------------|-----|----------|
| Collins | HFS-700 HF Comm | 7/13/2007 | ATA | 23-10-70 | 0771 | 6 | 10/15/1993 | 36 | 3/6/2014 |
| Collins | HFS-700 HF Comm | 7/13/2007 | ATA | 23-10-74 | 0775 | 5 | 11/15/1993 | 46 | 3/3/2014 |

TPS Number: TP-0649-65

TP Program #: 60-0649-65 **Version:** 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Collins | ADF-900 ADF Rcvr | 2/6/2012 | ATA | 34-53-94 | 0810 | 18 | 2/11/2015 | | |

TPS Number: TP-0649-66

TP Program #: 60-0649-66 **Version:** 1.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | HG480B DADC | 11/11/2006 | ATA | 34-11-02 | 3436 | 1 | 11/1/1998 | | |

TPS Number: TP-0649-67

TP Program #: 60-0649-67 **Version:** 2.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------------|-------------|-------|-------------|------|------|------------|-----|----------|
| Collins | TPR-720/TPR-900 Mode-S | 3/16/2018 | ATA | 34-50-74 | 0775 | 23 | 12/11/2017 | | |
| Collins | TPR-720/TPR-900 Mode-S | 3/16/2018 | ATA | 34-50-92 | 0776 | 1 | 12/20/1996 | 37 | 5/5/2015 |
| Collins | TPR-720/TPR-900 Mode-S | 3/16/2018 | ADATE | 832-1631 | | -005 | | | |

TPS Status Report



TPS Number: TP-0649-68

TP Program #: 60-0649-68 **Version:** 1.8

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------|-------------|-------|-------------|-------|------|------------|-----|----------|
| Collins | LRA-700 Radio Alt | 1/7/2010 | ATA | 34-47-70 | .0771 | 29 | 12/19/2014 | | |
| Collins | LRA-700 Radio Alt | 1/7/2010 | ATA | 34-47-73 | .0775 | 28 | 1/14/2015 | | |

TPS Number: TP-0649-69

TP Program #: 60-0649-69 **Version:** 1.8

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | ILS-900 ILS | 11/13/2008 | ATA | 34-36-90 | .0776 | 13 | 5/12/2011 | | |

TPS Number: TP-0649-71

TP Program #: 60-0649-71 **Version:** 1.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------------------|-------------|-------|-------------|-------|------|-----------|-----|-----------|
| Collins | RMI-733 Radio Mag Ind | 1/23/2006 | ATA | 34-22-74 | .0770 | 8 Ob | 10/1/1996 | 34 | 4/17/2008 |

TPS Number: TP-0649-72

TP Program #: 60-0649-72 **Version:** 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-----------|-------------|-------|-------------|------|------|------------|-------|-----------|
| Honeywell | GPWC Mk 5 | 3/7/2011 | ATA | 34-45-23 | 0494 | 6 | 12/12/2005 | 34-14 | 7/13/2006 |
| Honeywell | GPWC Mk 5 | 3/7/2011 | ATA | 34-45-25 | 0538 | 4 | 3/31/2006 | | |
| Honeywell | GPWC Mk 5 | 3/7/2011 | ATA | 34-45-27 | 0606 | 10 | 2/10/2006 | | |
| Honeywell | GPWC Mk 5 | 3/7/2011 | ATA | 34-45-30 | 0618 | 10 | 1/27/2006 | 34-16 | 1/22/2007 |
| Honeywell | GPWC Mk 5 | 3/7/2011 | ATA | 34-45-34 | 0652 | 2 | 3/17/2006 | | |

TPS Status Report



TPS Number: TP-0649-73

TP Program #: 60-0649-73 **Version:** 2.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | VOR-900 VOR | 9/24/2012 | ATA | 34-55-94 | .081C | 20 | 4/14/2015 | | |

TPS Number: TP-0649-74

TP Program #: 60-0649-74 **Version:** 2.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| ACSS | XS-950 Mode-S | 1/16/2012 | ATA | 34-52-08 | | 016 | 4/30/2105 | | |
| ACSS | XS-950 Mode-S | 1/16/2012 | MISC | 9000903-007 | | V | 4/28/2015 | | |
| ACSS | XS-950 Mode-S | 1/16/2012 | TRD | IT7517800 | | AV | 7/23/2014 | | |

TPS Number: TP-0649-75

TP Program #: 60-0649-75 **Version:** 3.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| ACSS | RT-950 TCAS | 8/13/2012 | ATA | 34-43-11 | | 13 | 1/30/2012 | | |
| ACSS | RT-950 TCAS | 8/13/2012 | ATA | IT7517900 | | AM | 6/27/2012 | | |

TPS Number: TP-0649-76

TP Program #: 60-0649-76 **Version:** 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | 51RV-4/5 VOR/ILS | 5/21/2011 | ATA | 34-35-10 | .0817 | 1 | 4/12/2012 | | |

TPS Status Report



TPS Number: TP-0649-77

TP Program #: 60-0649-77 **Version:** 3.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | GLU-920 MMR | 1/16/2012 | ATA | 34-70-09 | .081C | 38 | 7/24/2015 | | |

TPS Number: TP-0649-78

TP Program #: 60-0649-78 **Version:** 1.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| GE | 760SUE Autothrottle | 6/25/2014 | ATA | 22-30-16 | | 12 | 10/2/2015 | | |
| GE | 760SUE Autothrottle | 6/25/2014 | ATLAS | SSP31516 | | -1 | | | |

TPS Number: TP-0649-79

TP Program #: 60-0649-79 **Version:** 1.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | DCP-7000 Control Panel | 9/2/2008 | ATA | 31-61-57 | .081C | 2 | 7/13/2010 | | |
| Collins | DCP-7000 Control Panel | 9/2/2008 | ADATE | 995-0137 | | -110 | | | |

TPS Number: TP-0649-80

TP Program #: 60-0649-80 **Version:** 1.10

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------------------|-------------|-------|-------------|-------|------|-----------|-----|-----------|
| Collins | DSP-7000 Switch Panel | 9/20/2004 | ATA | 31-61-45 | .0774 | 0 | 8/1/1988 | 9 | 1/12/2006 |

TPS Status Report



TPS Number: TP-0649-81

TP Program #: 60-0649-81 **Version:** 1.8

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | LRA-900 Radio Altimeter | 2/24/2012 | ATA | 34-47-95 | .081C | 14 | 3/28/2012 | | |

TPS Number: TP-0649-82

TP Program #: 60-0649-82 **Version:** 1.8

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------|-------------|-------|--------------|------|-------|-----------|-------|-----------|
| Honeywell | EGPWC Mk 5 | 8/17/2018 | ATA | 34-45-36 | | 36 OB | 7/30/2008 | 34-20 | 6/13/2011 |
| Honeywell | EGPWC Mk 5 | 8/17/2018 | ATLAS | 996-5003-550 | | E | 6/10/2004 | | |

TPS Number: TP-0649-85

TP Program #: 60-0649-85 **Version:** 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | HFS-900 HF Comm | 3/11/2010 | ATA | 23-10-90 | .0817 | 8 | 6/18/2012 | | |

TPS Number: TP-0649-86

TP Program #: 60-0649-86 **Version:** 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| ACSS | VSI/TRA Display | 8/9/2011 | ATA | 22-54-01 | | 14 | 3/15/2009 | | |

TPS Status Report



TPS Number: TP-0649-87

TP Program #: 60-0649-87

Version: 1.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------|-------------|-------|-------------|-------|------|------------|-----|----------|
| Collins | RDMI-743 RMI | 6/11/2005 | ATA | 34-22-73 | .077C | 26 | 12/20/2011 | | |
| Collins | RDMI-743 RMI | 6/11/2005 | ADATE | 826-5263 | | -110 | | | |

TPS Number: TP-0649-88

TP Program #: 60-0649-88

Version: 1.5

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | GMLU-930 MMR | 3/1/2006 | ATA | 34-70-22 | .078C | 7 | 3/24/2008 | | |
| Collins | GMLU-930 MMR | 3/1/2006 | ADATE | 815-2486 | | -005 | | | |

TPS Number: TP-0649-89

TP Program #: 60-0649-89

Version: 2.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|----------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | TPR-901 Mode-S | 3/13/2019 | ATA | 34-50-99 | .081C | 24 | 8/2/2018 | | |
| Collins | TPR-901 Mode-S | 3/13/2019 | ATA | 389-0091 | | -001 | | | |
| Collins | TPR-901 Mode-S | 3/13/2019 | ADATE | 815-4752 | | -015 | | | |

TPS Status Report



TPS Number: TP-0649-90

TP Program #: 60-0649-90 **Version:** 2.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------|-------------|-------|-------------|-------|------|------------|-----|----------|
| Collins | TTR-921 TCAS | 9/2/2014 | MPS | 04-7021-06 | | 3.3 | | | |
| Collins | TTR-921 TCAS | 9/2/2014 | ATA | 34-40-48 | .081C | 20 | 10/30/2015 | | |
| Collins | TTR-921 TCAS | 9/2/2014 | ADATE | 826-7021 | | -034 | | | |

TPS Number: TP-0649-92

TP Program #: 60-0649-92 **Version:** 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | HFS-900D HF Comm | 5/13/2009 | ATA | 23-11-83 | .081C | 18 | 3/12/2012 | | |

TPS Number: TP-0649-93

TP Program #: 60-0649-93 **Version:** 1.00

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|------------------|-------------|-------|-------------|-------|------|-----------|-----|-----------|
| Collins | 628T-2/A HF Comm | 5/6/2004 | ATA | 23-10-12 | .0771 | 5 | 7/10/1992 | 32 | 4/12/2004 |

TPS Number: TP-0649-94

TP Program #: 60-0649-94 **Version:** 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|---------------------|-------------|-------|-------------|-------|------|-----------|-----|----------|
| Collins | TTR-92x P/N Utility | 5/22/2013 | ATA | 34-40-86 | .077C | 26 | 8/9/2011 | | |
| Collins | TTR-92x P/N Utility | 5/22/2013 | ADATE | 826-7021 | | -034 | | | |

TPS Status Report



TPS Number: TP-0649-95

TP Program #: 60-0649-95 **Version:** 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Collins | MCP-770 MCP | 12/21/2006 | ATA | 22-12-75 | 0777 | 2 | 5/7/1997 | 17 | 8/2/2005 |
| Collins | MCP-770 MCP | 12/21/2006 | ADATE | 832-1121 | | -005 | | | |

TPS Number: TP-0649-96

TP Program #: 60-0649-96 **Version:** 1.8

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| GE | 2584 LCD CDU | 4/12/2017 | ATLAS | 34-61-14 | 2 | 13 | 9/16/2016 | | |
| GE | 2584 LCD CDU | 4/12/2017 | ATA | 34-61-14 | 1 | 27 | 9/30/2016 | | |

TPS Number: TP-0649-97

TP Program #: 60-0649-97 **Version:** 2.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------|-------------|-------|-------------|------|------|-----------|-----|----------|
| GE | 2907C FMC | 12/6/2017 | ATA | 34-61-15 | 1 | 22 | 1/5/2018 | | |
| GE | 2907C FMC | 12/6/2017 | ATLAS | 34-61-15 | 2 | 12 | 1/5/2018 | | |

TPS Number: TP-0717-00

TP Program #: 60-0717-00 **Version:** 1.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------|-------------|-------|-------------|------|------|------------|-----|----------|
| Crane | Skid Control Unit | 8/29/2006 | ATA | 32-42-90 | | | 10/31/1985 | | |
| Crane | Skid Control Unit | 8/29/2006 | ATA | 32-42-93 | | 3 | 6/15/1990 | | |

TPS Status Report



TPS Number: TP-0717-01

TP Program #: 60-0717-01 **Version:** 1.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | HG480E DADC | 12/6/2007 | ATA | 34-14-71 | 3436 | 005 | 4/16/2007 | | |

TPS Number: TP-0717-02

TP Program #: 60-0717-02 **Version:** 1.7

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-----------|-------------|-------|-------------|------|------|-----------|-----|----------|
| GE | 2907A FMC | 9/8/2015 | ATLAS | 34-61-12 | 1A | 5 | 8/15/2014 | | |

TPS Number: TP-0717-03

TP Program #: 60-0717-03 **Version:** 1.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|--------------|-------------|-------|-------------|-------|------|------------|-----|------------|
| Collins | TPR-710A ATC | 3/20/2006 | ATA | 34-50-70 | .0771 | 4 | 12/20/1999 | 23 | 11/16/2006 |

TPS Number: TP-0717-06

TP Program #: 60-0717-06 **Version:** 1.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------|-------------|-------|-------------|------|------|-----------|-----|-----------|
| Thales | ERT-530 Radio Alt | 8/11/2011 | ATA | 34-42-34 | | 18 | 9/30/2009 | | |
| Thales | ERT-530 Radio Alt | 8/11/2011 | ATA | 34-42-57 | | 6 | 8/31/2009 | 6 | 12/3/2009 |

TPS Status Report



TPS Number: TP-0717-07

TP Program #: 60-0717-07

Version: 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|------------|-------------|-------|---------------|-------|------|-----------|-----|----------|
| Honeywell | SP-300 FCC | 5/23/2013 | ATA | 22-10-78 | 1142 | 12 | 4/1/2010 | | |
| Honeywell | SP-300 FCC | 5/23/2013 | ATA | 22-11-75 | 1142- | 9 | 4/1/1995 | | |
| Honeywell | SP-300 FCC | 5/23/2013 | ATLAS | SA4051600-913 | | F | 2/12/2004 | | |
| Honeywell | SP-300 FCC | 5/23/2013 | ATLAS | SA4051600-914 | | D | 2/12/2004 | | |

TPS Number: TP-0717-08

TP Program #: 60-0717-08

Version: 1.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------|-------------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Collins | VHF-900 Alignment | 8/22/2008 | ATA | 23-12-90 | 0776 | 30 | 7/17/2008 | | |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-13

TP Program #: 60-0653-13 **Version:** 3.00 **Date:** 2/24/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-------------------------|-------|-------------|------|------|-----------|-------|----------|
| HONEYWELL KDM-7000B DME | ATA | 34-50-10 | | 5 | 6/1/1992 | 34-57 | 4/4/2006 |

TPS Number: TP-0653-14

TP Program #: 60-0653-14 **Version:** 2.20 **Date:** 12/23/2002

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------|-------|----------------|------|------|-----------|------|-----------|
| HONEYWELL KDM-7070 DME | MISC | 006-05561-0003 | | 3 | 10/1/1990 | 34-3 | 11/1/1995 |

TPS Number: TP-0653-15

TP Program #: 60-0653-15 **Version:** 2.00 **Date:** 1/31/2000

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------------|-------|-------------|------|------|-----------|------|-----------|
| HONEYWELL KDM-7000B 521D DME | ATA | 34-50-11 | | 2 | 1/1/1993 | 34-6 | 11/1/1995 |

TPS Number: TP-0653-16

TP Program #: 60-0653-16 **Version:** 2.00 **Date:** 5/3/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------|-------|----------------|------|------|-----------|------|-----------|
| HONEYWELL KDM-7060 DME | ATLAS | 006-05561-0003 | | 3 | 10/1/1990 | 34-3 | 11/1/1995 |

TPS Number: TP-0653-17

TP Program #: 60-0653-17 **Version:** 3.1 **Date:** 4/7/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|---------------------------------|-------|-------------|------|------|-----------|-----|----------|
| BOEING DIGITAL STALL WARNING CO | ATA | 27-32-48 | | 32 | 3/1/2004 | | |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-18

TP Program #: 60-0653-18 **Version:** 2.20 **Date:** 2/19/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------|-------|-------------|------|------|-----------|-------|-----------|
| HONEYWELL KNR-6030 VOR | ATA | 34-50-12 | | 4 | 5/1/1995 | 34-18 | 12/5/2001 |

TPS Number: TP-0653-19

TP Program #: 60-0653-19 **Version:** 2.00 **Date:** 4/25/2000

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------------|-------|-------------|------|------|-----------|-------|----------|
| BOEING AUTOSLAT COMPUTER | ATA | 27-10-50 | | 17 | 7/7/1998 | 27-17 | |
| BOEING AUTOSLAT COMPUTER | ATA | 27-10-52 | | 18 | 12/1/1997 | 27-18 | |

TPS Number: TP-0653-21

TP Program #: 60-0653-21 **Version:** 3.3 **Date:** 7/8/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------|-------|-------------|-------------|------|-----------|-----|----------|
| COLLINS 51RV-1 VOR | ATA | 34-35-00 | 523-0736003 | 12 | 9/15/1978 | 28 | |

TPS Number: TP-0653-22

TP Program #: 60-0653-22 **Version:** 2.3 **Date:** 9/21/2007

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|---------------------|-------|-------------|-------------|------|------------|-----|-----------|
| COLLINS 51RV-2B VOR | ATA | 34-35-03 | 523-0760757 | 10 | 8/15/1992 | 26 | 8/15/2007 |
| COLLINS 51RV-2B VOR | ATA | 34-35-05 | 523-0760756 | 7 | 10/1/1992 | 18 | 7/26/2002 |
| COLLINS 51RV-2B VOR | ATA | 34-35-06 | | 7 | 10/15/1978 | 12 | 11/2/2007 |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-23

TP Program #: 60-0653-23 **Version:** 3.2 **Date:** 2/2/2007

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|---------------------------|-------|-------------|------|------|------------|--------|-----------|
| HONEYWELL RNA-34A VOR/ILS | ATA | 34-55-01 | 1 | 14 | 12/15/2004 | 34-160 | 1/18/2007 |
| HONEYWELL RNA-34A VOR/ILS | ATA | 34-55-36 | | 1 | 12/15/2004 | 34-83 | 2/8/2007 |

TPS Number: TP-0653-24

TP Program #: 60-0653-24 **Version:** 1.40 **Date:** 8/30/2002

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------------|-------|-------------|------|------|-----------|-------|-----------|
| HONEYWELL KTR-9100A VHF COMM | ATA | 23-20-02 | | 5 | 10/1/1991 | 23-36 | 10/3/2003 |

TPS Number: TP-0653-25

TP Program #: 60-0653-25 **Version:** 1.30 **Date:** 8/30/2002

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------|-------|-------------|-------------|------|-----------|-----|-----------|
| COLLINS 621A-3 ATC | ATA | 34-44-00 | 523-0756695 | 13 | 5/1/1996 | 44 | 3/20/2003 |

TPS Number: TP-0653-26

TP Program #: 60-0653-26 **Version:** 2.4 **Date:** 8/12/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------------|-------|-------------|-------------|------|------------|-----|-----------|
| COLLINS 621A-6/6A ATC | ATA | 34-50-00 | 523-0759616 | 11 | 12/15/1989 | 40 | 4/30/2001 |

TPS Number: TP-0653-27

TP Program #: 60-0653-27 **Version:** 2.3 **Date:** 10/17/2006

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------|-------|-------------|-------------|------|-----------|-----|----------|
| COLLINS 860E-5 DME | ATA | 34-52-12 | 523-0768230 | 16 | 6/15/2006 | | |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-28

TP Program #: 60-0653-28 **Version:** 2.2 **Date:** 7/18/2008

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|---------------------------|-------|-------------|------|------|-----------|-----|----------|
| HONEYWELL 4051601-9XX MCP | ATA | 22-11-76 | 2 | 13 | 3/15/2007 | | |
| HONEYWELL 4051601-9XX MCP | ATA | 22-11-85 | 2 | 9 | 2/15/2005 | | |

TPS Number: TP-0653-29

TP Program #: 60-0653-29 **Version:** 1.10 **Date:** 11/15/2000

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------------------|-------|-------------|------|------|-----------|-------|-----------|
| HONEYWELL KTR-9000 VHF COMM | ATA | 23-20-0 | | 7 | 7/1/1975 | 23-13 | 10/1/1997 |

TPS Number: TP-0653-30

TP Program #: 60-0653-30 **Version:** 1.10 **Date:** 2/28/2000

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------------------------|-------|-------------|------|------|-----------|-------|------------|
| HONEYWELL RTA-43A VHF COMM | ATA | 23-20-33 | | 8 | 3/1/1993 | 23-39 | 10/12/1999 |

TPS Number: TP-0653-31

TP Program #: 60-0653-31 **Version:** 1.20 **Date:** 6/23/2000

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------|-------|-------------|------|------|-----------|-------|-----------|
| HONEYWELL KXP-7500 ATC | ATA | 34-50-08 | | 6 | 6/1/1990 | 34-16 | 9/18/2000 |

TPS Number: TP-0653-33

TP Program #: 60-0653-33 **Version:** 2.00 **Date:** 3/17/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------------------------|-------|-------------|------|------|-----------|-------|----------|
| HONEYWELL RIA-32A ILS RCVR | ATA | 34-36-31 | | 9 | 9/1/2002 | 34-50 | 6/6/2003 |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-34

TP Program #: 60-0653-34 **Version:** 3.1 **Date:** 11/17/2006

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------------------------|-------|-------------|-------------|------|-----------|-----|------------|
| COLLINS 618M-5/5A VHF COMM | ATA | 23-26-03 | 523-0778445 | 1 | 4/1/1998 | 23 | 12/12/2008 |

TPS Number: TP-0653-36

TP Program #: 60-0653-36 **Version:** 2.1 **Date:** 8/10/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------------|-------|-------------|-------------|------|------------|-----|-----------|
| COLLINS 51Y-7/A/C ADF | ATA | 34-53-01 | 523-0762367 | 6 | 8/2/1993 | 28 | 3/14/2000 |
| COLLINS 51Y-7/A/C ADF | ATA | 34-53-04 | 523-0766943 | 4 | 11/15/1993 | 40 | 9/21/2005 |
| COLLINS 51Y-7/A/C ADF | ATA | 34-53-08 | 523-0773742 | 4 | 11/15/1993 | 15 | 1/11/2008 |

TPS Number: TP-0653-38

TP Program #: 60-0653-38 **Version:** 1.4 **Date:** 5/2/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------|-------|-------------|-------------|------|-----------|-----|----------|
| COLLINS 860E-4 DME | ATA | 34-52-14 | 523-0768229 | 4 | 5/30/2000 | | |

TPS Number: TP-0653-40

TP Program #: 60-0653-40 **Version:** 1.50 **Date:** 10/10/2002

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------------------------|-------|-------------|-------------|------|------------|-----|----------|
| COLLINS 618M-3/3A VHF COMM | ATA | 23-26-00 | 523-0764898 | 10 | 10/27/1995 | 58 | 5/6/2002 |

TPS Number: TP-0653-41

TP Program #: 60-0653-41 **Version:** 2.00 **Date:** 10/23/2002

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------------------------|-------|-------------|------|------|-----------|-------|-----------|
| HONEYWELL RVA-33A VOR RCVR | ATA | 34-55-31 | | 6 | 12/1/1982 | 34-18 | 1/31/2001 |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-42

TP Program #: 60-0653-42 **Version:** 2.00 **Date:** 1/7/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|---------------------------|-------|-------------|-------------|------|-----------|-----|------------|
| COLLINS 51Y-4/4A ADF RCVR | ATA | 34-34-01 | 523-0755938 | 8 | 9/15/1989 | 10 | 11/13/1996 |

TPS Number: TP-0653-43

TP Program #: 60-0653-43 **Version:** 2.00 **Date:** 3/25/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------|-------|-------------|-------------|------|-----------|-----|----------|
| COLLINS 51Z-4 MKR RCVR | ATA | 34-36-00 | 523-0755846 | 10 | 4/1/1996 | 24 | 4/8/2004 |

TPS Number: TP-0653-44

TP Program #: 60-0653-44 **Version:** 1.50 **Date:** 4/3/2003

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|----------------------|-------|-------------|------|------|------------|-------|----------|
| HONEYWELL GPWC MK II | ATA | 34-45-17 | | 11 | 12/16/1997 | 34-27 | 5/9/2002 |

TPS Number: TP-0653-45

TP Program #: 60-0653-45 **Version:** 2.00 **Date:** 11/8/2000

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------------------|-------|-------------|-------------|------|-----------|-----|-----------|
| COLLINS 618M-2B/2D VHF COMM | ATA | 23-24-00 | 523-0758990 | 13 | 4/1/1986 | 15 | 9/23/1997 |

TPS Number: TP-0653-46

TP Program #: 60-0653-46 **Version:** 2.00 **Date:** 5/30/2007

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------------|-------|-------------|-------------|------|-----------|-----|------------|
| COLLINS 618T-2/5 HF COMM | ATA | 23-10-00 | 520-5970003 | 16 | 5/1/1985 | 21 | 12/20/2000 |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-48

TP Program #: 60-0653-48 **Version:** 2.00 **Date:** 3/4/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------|-------|-------------|-------------|------|-----------|-----|------------|
| COLLINS 628T-1 HF COMM | ATA | 23-10-10 | 523-0767803 | 7 | 7/1/1992 | 22 | 11/14/2002 |

TPS Number: TP-0653-50

TP Program #: 60-0653-50 **Version:** 1.40 **Date:** 8/28/2007

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|---------------------------|-------|-------------|------|------|-----------|-----|----------|
| HONEYWELL 4051601-937 MCP | ATA | 22-11-84 | 2 | 11 | 1/15/2005 | | |

TPS Number: TP-0653-52

TP Program #: 60-0653-52 **Version:** 2.10 **Date:** 8/3/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------------|-------|-------------|------|------|-----------|-----|----------|
| ACSS 4066010-90X TCAS | ATA | 34-43-04D | | 3 | 1/1/2000 | | |

TPS Number: TP-0653-56

TP Program #: 60-0653-56 **Version:** 1.20 **Date:** 1/23/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------------|-------|-------------|------|------|-----------|-----|----------|
| HONEYWELL ARN-123 VOR | MISC | 4008850 | | T | 5/2/2001 | | |

TPS Number: TP-0653-57

TP Program #: 60-0653-57 **Version:** 2.4 **Date:** 2/10/2005

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------------------|-------|-------------|------|------|-----------|-----|-----------|
| COLLINS 860F-4 RADIO ALTIMETER | ATA | 34-47-12 | | 8 | 2/1/1993 | 61 | 5/15/2007 |

IRIS 2000 HPBW TPS Status Report



TPS Number: TP-0653-60

TP Program #: 60-0653-60 **Version:** 2.00 **Date:** 8/13/2003

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------------------|-------|-------------|-------------|------|-----------|-----|-----------|
| COLLINS 860F-1 RADIO ALTIMETER | ATA | 34-47-05 | 523-0758870 | 10 | 9/15/1991 | 45 | 2/17/2007 |
| COLLINS 860F-1 RADIO ALTIMETER | ATA | 34-47-09 | 523-0763306 | 9 | 9/15/1991 | 33 | 5/10/2002 |
| COLLINS 860F-1 RADIO ALTIMETER | ATA | 34-47-11 | 523-0763982 | 7 | 9/15/1991 | 40 | 2/24/2003 |

TPS Number: TP-0653-61

TP Program #: 60-0653-61 **Version:** 3.00 **Date:** 6/2/2003

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|------------------------|-------|-------------|------|------|-----------|-----|----------|
| COLLINS 346D-2B PA AMP | ATA | 23-32-02 | | 5 | 6/15/1993 | 39 | |

TPS Number: TP-0653-62

TP Program #: 60-0653-62 **Version:** 2.00 **Date:** 8/5/2004

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-------------------------|-------|---------------|------|------|-----------|-----|----------|
| ACSS 4061400-90X MODE-S | ATA | 34-44-03C | | | | | |
| ACSS 4061400-90X MODE-S | ATLAS | SA4061400-905 | | D | | | |

TPS Number: TP-0653-65

TP Program #: 60-0653-65 **Version:** 1.20 **Date:** 6/20/2003

| LRU OEM: LRU Name: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|--------------------|-------|-------------|-------------|------|-----------|-----|-----------|
| COLLINS ILS-70 ILS | ATA | 34-36-03 | 523-0764437 | 6 | 2/2/1998 | 30 | 1/20/2003 |

LRUs Tested Sorted By LRU Part Number

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|------------------------------|----------------|
| 064-01076-0101 | Honeywell KTR909B UHF Comm | 60-0649-22 |
| 064-1004-00 | Honeywell KTR-9000 VHF Comm | 60-0653-29 |
| 064-1005-02 | Honeywell KTR-9100A VHF Comm | 60-0653-24 |
| 064-1005-03 | Honeywell KTR-9100A VHF Comm | 60-0653-24 |
| 064-1005-04 | Honeywell KTR-9100A VHF Comm | 60-0653-24 |
| 064-1005-12 | Honeywell KTR-9100A VHF Comm | 60-0653-24 |
| 064-1005-14 | Honeywell KTR-9100A VHF Comm | 60-0653-24 |
| 064-1005-15 | Honeywell KTR-9100A VHF Comm | 60-0653-24 |
| 064-50000-0101 | Honeywell RTA-44D Alignment | 60-0649-3A |
| 064-50000-0101 | Honeywell RTA-44D VHF Comm | 60-0649-30 |
| 064-50000-0202 | Honeywell RTA-44D Alignment | 60-0649-3A |
| 064-50000-0202 | Honeywell RTA-44D VHF Comm | 60-0649-30 |
| 064-50000-0303 | Honeywell RTA-44D VHF Comm | 60-0649-30 |
| 064-50001-0101 | Honeywell RTA-83A VHF Comm | 60-0649-31 |
| 066-01127-0000 | Honeywell TRA-67A ATC/Mode-S | 60-0649-36 |
| 066-01127-1101 | Honeywell TRA-67A ATC/Mode-S | 60-0649-36 |
| 066-01127-1301 | Honeywell TRA-67A ATC/Mode-S | 60-0649-36 |
| 066-01127-1401 | Honeywell TRA-67A ATC/Mode-S | 60-0649-36 |
| 066-01127-1402 | Honeywell TRA-67A ATC/Mode-S | 60-0649-36 |
| 066-01127-1601 | Honeywell TRA-67A ATC/Mode-S | 60-0649-36 |
| 066-01127-1602 | Honeywell TRA-67A ATC/Mode-S | 60-0649-36 |
| 066-1019-23 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-27 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-55 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-57 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-63 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-X1 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-X2 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-X5 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1019-X6 | Honeywell KDM-7000B DME | 60-0653-13 |
| 066-1056-00 | Honeywell KXP-7500 ATC | 60-0653-31 |
| 066-1056-01 | Honeywell KXP-7500 ATC | 60-0653-31 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------------|----------------|
| 066-1060-01 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 066-1060-04 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 066-1060-12 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 066-1060-13 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 066-1060-18 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 066-1060-48 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 066-1060-50 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 066-1093-00 | Honeywell KDM-7060 DME | 60-0653-16 |
| 066-1093-02 | Honeywell KDM-7060 DME | 60-0653-16 |
| 066-1093-10 | Honeywell KDM-7060 DME | 60-0653-16 |
| 066-1093-11 | Honeywell KDM-7060 DME | 60-0653-16 |
| 066-1093-20 | Honeywell KDM-7060 DME | 60-0653-16 |
| 066-1093-30 | Honeywell KDM-7060 DME | 60-0653-16 |
| 066-1094-01 | Honeywell KDM-7070 DME | 60-0653-14 |
| 066-1094-02 | Honeywell KDM-7070 DME | 60-0653-14 |
| 066-1094-03 | Honeywell KDM-7070 DME | 60-0653-14 |
| 066-3057-10 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-3057-11 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-3057-12 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-3057-13 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-3057-14 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-3057-15 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-3057-16 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-3057-17 | Honeywell KDM-7000B 521D DME | 60-0653-15 |
| 066-50000-0102 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0107 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0108 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0108 | Aeroflex TPS Utility for TPA-81A | 60-0649-99 |
| 066-50000-0109 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0203 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0207 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0208 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0301 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0302 | Honeywell TPA-81A TCAS | 60-0649-35 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|------------------------|----------------|
| 066-50000-0307 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0308 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0402 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0405 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0407 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0408 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0504 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0507 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0508 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0606 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0607 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0608 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0708 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0808 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-0910 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1108 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1109 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1208 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1408 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1508 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1608 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1708 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1910 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-1911 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2120 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2121 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2220 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2221 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2320 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2321 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2620 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2621 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2720 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50000-2721 | Honeywell TPA-81A TCAS | 60-0649-35 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------|----------------|
| 066-50000-2930 | Honeywell TPA-81A TCAS | 60-0649-35 |
| 066-50006-0101 | Honeywell RIA-35B Align | 60-0649-2A |
| 066-50006-0101 | Honeywell RIA-35B ILS | 60-0649-27 |
| 066-50006-0202 | Honeywell RIA-35B ILS | 60-0649-27 |
| 066-50006-0202 | Honeywell RIA-35B Align | 60-0649-2A |
| 066-50006-1101 | Honeywell RIA-35B ILS | 60-0649-27 |
| 066-50006-1202 | Honeywell RIA-35B ILS | 60-0649-27 |
| 066-50012-0101 | Honeywell RVA-36B Align | 60-0649-2B |
| 066-50012-0101 | Honeywell RVA-36B VOR | 60-0649-28 |
| 066-50012-0202 | Honeywell RVA-36B Align | 60-0649-2B |
| 066-50012-0202 | Honeywell RVA-36B VOR | 60-0649-28 |
| 066-50012-0212 | Honeywell RVA-36B VOR | 60-0649-28 |
| 066-50012-0303 | Honeywell RVA-36B VOR | 60-0649-28 |
| 066-50014-0101 | Honeywell DFA-75B Align | 60-0649-2C |
| 066-50014-0101 | Honeywell DFA-75B ADF Rcvr | 60-0649-29 |
| 066-50014-0202 | Honeywell DFA-75B ADF Rcvr | 60-0649-29 |
| 066-50014-0202 | Honeywell DFA-75B Align | 60-0649-2C |
| 1149-00-01 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 1149-00-04 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 1149-00-12 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 1149-00-13 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 1149-00-18 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 1149-00-48 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 1149-00-50 | Honeywell KNR-6030 VOR | 60-0653-18 |
| 166805-03-01 | GE 2904 FMC | 60-0649-48 |
| 166805-04-01 | GE 2904 FMC | 60-0649-48 |
| 166805-05-01 | GE 2904 FMC | 60-0649-48 |
| 166805-06-01 | GE 2904 FMC | 60-0649-48 |
| 166805-07-01 | GE 2904 FMC | 60-0649-48 |
| 166805-08-01 | GE 2904 FMC | 60-0649-48 |
| 166805-09-01 | GE 2904 FMC | 60-0649-48 |
| 166805-10-01 | GE 2904 FMC | 60-0649-48 |
| 166805-11-01 | GE 2904 FMC | 60-0649-48 |
| 166805-12-01 | GE 2904 FMC | 60-0649-48 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|------------------|----------------|
| 166805-13-01 | GE 2904 FMC | 60-0649-48 |
| 166805-14-01 | GE 2904 FMC | 60-0649-48 |
| 166891-01-01 | GE 2577B/D/F CDU | 60-0649-37 |
| 167550-01-01 | GE 2577B/D/F CDU | 60-0649-37 |
| 167550-02-01 | GE 2577B/D/F CDU | 60-0649-37 |
| 167726-03-01 | GE 2904 FMC | 60-0649-48 |
| 167726-04-01 | GE 2904 FMC | 60-0649-48 |
| 167726-05-01 | GE 2904 FMC | 60-0649-48 |
| 167726-06-01 | GE 2904 FMC | 60-0649-48 |
| 167726-07-01 | GE 2904 FMC | 60-0649-48 |
| 167726-08-01 | GE 2904 FMC | 60-0649-48 |
| 167726-09-01 | GE 2904 FMC | 60-0649-48 |
| 167726-10-01 | GE 2904 FMC | 60-0649-48 |
| 167726-11-01 | GE 2904 FMC | 60-0649-48 |
| 167726-13-01 | GE 2904 FMC | 60-0649-48 |
| 167726-14-01 | GE 2904 FMC | 60-0649-48 |
| 167726-15-01 | GE 2904 FMC | 60-0649-48 |
| 167726-16-01 | GE 2904 FMC | 60-0649-48 |
| 167726-17-01 | GE 2904 FMC | 60-0649-48 |
| 167726-18-01 | GE 2904 FMC | 60-0649-48 |
| 167726-19-01 | GE 2904 FMC | 60-0649-48 |
| 167726-20-01 | GE 2904 FMC | 60-0649-48 |
| 167726-21-01 | GE 2904 FMC | 60-0649-48 |
| 167726-22-01 | GE 2904 FMC | 60-0649-48 |
| 167726-23-01 | GE 2904 FMC | 60-0649-48 |
| 167726-24-01 | GE 2904 FMC | 60-0649-48 |
| 168925-02-01 | GE 2904 FMC | 60-0649-48 |
| 168925-03-01 | GE 2904 FMC | 60-0649-48 |
| 168925-04-01 | GE 2904 FMC | 60-0649-48 |
| 168925-05-01 | GE 2904 FMC | 60-0649-48 |
| 168925-06-01 | GE 2904 FMC | 60-0649-48 |
| 168925-07-01 | GE 2904 FMC | 60-0649-48 |
| 168925-08-01 | GE 2904 FMC | 60-0649-48 |
| 168925-09-01 | GE 2904 FMC | 60-0649-48 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------|----------------|
| 168925-10-01 | GE 2904 FMC | 60-0649-48 |
| 168925-11-01 | GE 2904 FMC | 60-0649-48 |
| 168925-12-01 | GE 2904 FMC | 60-0649-48 |
| 168925-13-01 | GE 2904 FMC | 60-0649-48 |
| 168925-14-01 | GE 2904 FMC | 60-0649-48 |
| 168925-15-01 | GE 2904 FMC | 60-0649-48 |
| 168925-16-01 | GE 2904 FMC | 60-0649-48 |
| 170089-01-01 | GE 2577B/D/F CDU | 60-0649-37 |
| 170089-02-01 | GE 2577B/D/F CDU | 60-0649-37 |
| 171497-01-01 | GE 2907A FMC | 60-0717-02 |
| 171497-04-01 | GE 2907A FMC | 60-0717-02 |
| 171497-05-01 | GE 2907A FMC | 60-0717-02 |
| 174101-01-01 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-01-02 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-01-03 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-02-01 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-02-02 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-02-03 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-03-01 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-03-02 | GE 2584 LCD CDU | 60-0649-96 |
| 174101-03-03 | GE 2584 LCD CDU | 60-0649-96 |
| 176200-01-01 | GE 2907C FMC | 60-0649-97 |
| 2041167-3701 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041167-3702 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041167-3703 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041167-3704 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041167-3705 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041167-3706 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041167-3707 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041167-3709 | Honeywell DMA-37A DME | 60-0649-20 |
| 2041168-7501 | Honeywell DFA-75A ADF Rcvr | 60-0649-60 |
| 2041168-7506 | Honeywell DFA-75A ADF Rcvr | 60-0649-60 |
| 2041168-7510 | Honeywell DFA-75A ADF Rcvr | 60-0649-60 |
| 2041168-7511 | Honeywell DFA-75A ADF Rcvr | 60-0649-60 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------|----------------|
| 2041168-7512 | Honeywell DFA-75A ADF Rcvr | 60-0649-60 |
| 2041168-7513 | Honeywell DFA-75A ADF Rcvr | 60-0649-60 |
| 2041168-7514 | Honeywell DFA-75A ADF Rcvr | 60-0649-60 |
| 2041230-3503 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3504 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3514 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3515 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3516 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3517 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3518 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3519 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3520 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3521 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3522 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3523 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3525 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3526 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3527 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3528 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3529 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3530 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3531 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3532 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041230-3533 | Honeywell RIA-35A ILS Rcvr | 60-0649-46 |
| 2041231-3601 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3604 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3606 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3607 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3608 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3609 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3610 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3611 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3613 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3614 | Honeywell RVA-36A VOR/MB | 60-0649-47 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------|----------------|
| 2041231-3615 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3616 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3617 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3618 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3622 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041231-3623 | Honeywell RVA-36A VOR/MB | 60-0649-47 |
| 2041234-3401 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3407 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3408 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3409 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3412 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3415 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3418 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3419 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3421 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3422 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3426 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3432 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3433 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3434 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3437 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3440 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3442 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3443 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3445 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041234-3446 | Honeywell RNA-34A VOR/ILS | 60-0653-23 |
| 2041237-4401 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4406 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4407 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4408 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4410 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4411 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4412 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4413 | Honeywell RTA-44A VHF Comm | 60-0649-52 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|-------------------------------------|----------------|
| 2041237-4417 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4418 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4422 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4424 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4425 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4426 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4428 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4429 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4430 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4431 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4432 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2041237-4433 | Honeywell RTA-44A VHF Comm | 60-0649-52 |
| 2070724-3201 | Honeywell RIA-32A ILS Rcvr | 60-0653-33 |
| 2070724-3203 | Honeywell RIA-32A ILS Rcvr | 60-0653-33 |
| 2070724-3205 | Honeywell RIA-32A ILS Rcvr | 60-0653-33 |
| 2070724-3206 | Honeywell RIA-32A ILS Rcvr | 60-0653-33 |
| 2070750-3301 | Honeywell RVA-33A VOR Rcvr | 60-0653-41 |
| 2070750-3305 | Honeywell RVA-33A VOR Rcvr | 60-0653-41 |
| 2070750-3306 | Honeywell RVA-33A VOR Rcvr | 60-0653-41 |
| 2070750-3307 | Honeywell RVA-33A VOR Rcvr | 60-0653-41 |
| 2070945-4301 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4302 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4305 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4311 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4312 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4315 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4321 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4322 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4325 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4331 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4332 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2070945-4335 | Honeywell RTA-43A VHF Comm | 60-0653-30 |
| 2117388-05 | Honeywell Cabin Pressure Controller | 60-0649-25 |
| 2117388-06 | Honeywell Cabin Pressure Controller | 60-0649-25 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|-------------------------------------|----------------|
| 2117388-07 | Honeywell Cabin Pressure Controller | 60-0649-25 |
| 2117388-08 | Honeywell Cabin Pressure Controller | 60-0649-25 |
| 2117388-10 | Honeywell Cabin Pressure Controller | 60-0649-25 |
| 2117388-11 | Honeywell Cabin Pressure Controller | 60-0649-25 |
| 2233000-1 | Teledyne 2233000 DFDAU | 60-0649-23 |
| 2233000-1A | Teledyne 2233000 DFDAU | 60-0649-23 |
| 2233000-3 | Teledyne 2233000 DFDAU | 60-0649-23 |
| 2233000-3A | Teledyne 2233000 DFDAU | 60-0649-23 |
| 2233000-4 | Teledyne 2233000 DFDAU | 60-0649-23 |
| 2233000-4A | Teledyne 2233000 DFDAU | 60-0649-23 |
| 285T0001-69 | Boeing Audio Accessory Unit | 60-0649-41 |
| 3614306-3401 | Honeywell RNA-34AF VOR | 60-0649-19 |
| 3614306-3402 | Honeywell RNA-34AF VOR | 60-0649-19 |
| 4000937-6201 | Honeywell ARN-123 VOR | 60-0653-56 |
| 4000937-6202 | Honeywell ARN-123 VOR | 60-0653-56 |
| 4000937-6221 | Honeywell ARN-123 VOR | 60-0653-56 |
| 4000937-6222 | Honeywell ARN-123 VOR | 60-0653-56 |
| 4051600-912 | Honeywell SP-300 FCC | 60-0653-32 |
| 4051600-912 | Honeywell SP-300 FCC | 60-0717-07 |
| 4051600-913 | Honeywell SP-300 FCC | 60-0653-32 |
| 4051600-913 | Honeywell SP-300 FCC | 60-0717-07 |
| 4051600-914 | Honeywell SP-300 FCC | 60-0717-07 |
| 4051600-914 | Honeywell SP-300 FCC | 60-0653-32 |
| 4051600-923 | Honeywell SP-300 FCC | 60-0717-07 |
| 4051601-932 | Honeywell 4051601-9xx MCP | 60-0653-28 |
| 4051601-935 | Honeywell 4051601-9xx MCP | 60-0653-28 |
| 4051601-937 | Honeywell 4051601-937 MCP | 60-0653-50 |
| 4051601-938 | Honeywell 4051601-9xx MCP | 60-0653-28 |
| 4051601-940 | Honeywell 4051601-9xx MCP | 60-0653-28 |
| 4051601-945 | Honeywell 4051601-9xx MCP | 60-0653-28 |
| 4061100-901 | Honeywell HG480E DADC | 60-0653-55 |
| 4061100-901 | Honeywell HG480E DADC | 60-0717-01 |
| 4061400-903 | ACSS 4061400-90x Mode-S | 60-0653-62 |
| 4061400-904 | ACSS 4061400-90x Mode-S | 60-0653-62 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|-------------------------|----------------|
| 4061400-905 | ACSS 4061400-90x Mode-S | 60-0653-62 |
| 4066010-904 | ACSS 4066010-90x TCAS | 60-0653-52 |
| 4066010-905 | ACSS 4066010-90x TCAS | 60-0653-52 |
| 4066010-907 | ACSS 4066010-90x TCAS | 60-0653-52 |
| 4067241-801 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-802 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-803 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-804 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-805 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-806 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-840 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-841 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-842 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-843 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-844 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-845 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-860 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-861 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-862 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-863 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-864 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-865 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-880 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-881 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-882 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-883 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-884 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-885 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-890 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-891 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-892 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-893 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-894 | ACSS VSI/TRA Display | 60-0649-86 |
| 4067241-895 | ACSS VSI/TRA Display | 60-0649-86 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|--------------------------------|----------------|
| 42-719-01 | Crane Skid Control Unit | 60-0717-00 |
| 42-719-02 | Crane Skid Control Unit | 60-0717-00 |
| 522-1501-000 | Collins 618T-2/5 HF Comm | 60-0653-46 |
| 522-1501-041 | Collins 618T-2/5 HF Comm | 60-0653-46 |
| 522-1501-043 | Collins 618T-2/5 HF Comm | 60-0653-46 |
| 522-1501-044 | Collins 618T-2/5 HF Comm | 60-0653-46 |
| 522-1836-000 | Collins 51Y-4/4A ADF Rcvr | 60-0653-42 |
| 522-1836-013 | Collins 51Y-4/4A ADF Rcvr | 60-0653-42 |
| 522-2450-000 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-011 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-014 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-015 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-016 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-020 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-111 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-114 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-115 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2450-120 | Collins 51RV-1 VOR | 60-0653-21 |
| 522-2587-000 | Collins 51Y-4/4A ADF Rcvr | 60-0653-42 |
| 522-2587-013 | Collins 51Y-4/4A ADF Rcvr | 60-0653-42 |
| 522-2587-015 | Collins 51Y-4/4A ADF Rcvr | 60-0653-42 |
| 522-2703-000 | Collins 621A-3 ATC | 60-0653-25 |
| 522-2703-011 | Collins 621A-3 ATC | 60-0653-25 |
| 522-2703-012 | Collins 621A-3 ATC | 60-0653-25 |
| 522-2703-013 | Collins 621A-3 ATC | 60-0653-25 |
| 522-2996-000 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-2996-011 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-2996-013 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-2996-014 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-2996-015 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-2996-016 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-2996-017 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-2996-018 | Collins 51Z-4 Mkr Rcvr | 60-0653-43 |
| 522-3698-002 | Collins 860F-1 Radio Altimeter | 60-0653-60 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|--------------------------------|----------------|
| 522-3698-003 | Collins 860F-1 Radio Altimeter | 60-0653-60 |
| 522-3698-004 | Collins 860F-1 Radio Altimeter | 60-0653-60 |
| 522-3698-006 | Collins 860F-1 Radio Altimeter | 60-0653-60 |
| 522-3698-011 | Collins 860F-1 Radio Altimeter | 60-0653-60 |
| 522-3698-013 | Collins 860F-1 Radio Altimeter | 60-0653-60 |
| 522-3698-014 | Collins 860F-1 Radio Altimeter | 60-0653-60 |
| 522-4088-001 | Collins 618M-2B/2D VHF Comm | 60-0653-45 |
| 522-4088-004 | Collins 618M-2B/2D VHF Comm | 60-0653-45 |
| 522-4088-203 | Collins 618M-2B/2D VHF Comm | 60-0653-45 |
| 522-4088-204 | Collins 618M-2B/2D VHF Comm | 60-0653-45 |
| 522-4089-004 | Collins 618M-2B/2D VHF Comm | 60-0653-45 |
| 522-4089-005 | Collins 618M-2B/2D VHF Comm | 60-0653-45 |
| 522-4089-204 | Collins 618M-2B/2D VHF Comm | 60-0653-45 |
| 522-4280-001 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-005 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-007 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-008 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-101 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-102 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-105 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-107 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-108 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4280-109 | Collins 51RV-2B VOR | 60-0653-22 |
| 522-4977-001 | Collins 51RV-2B VOR | 60-0653-22 |
| 622-1181-001 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1181-002 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1181-003 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1181-004 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1181-005 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1181-006 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1181-008 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1181-009 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-001 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-002 | Collins 618M-3/3A VHF Comm | 60-0653-40 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------|----------------|
| 622-1396-003 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-010 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-011 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-101 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-102 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-203 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-205 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-206 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-1396-208 | Collins 618M-3/3A VHF Comm | 60-0653-40 |
| 622-2224-001 | Collins 621A-6/6A ATC | 60-0653-26 |
| 622-2224-002 | Collins 621A-6/6A ATC | 60-0653-26 |
| 622-2224-003 | Collins 621A-6/6A ATC | 60-0653-26 |
| 622-2224-101 | Collins 621A-6/6A ATC | 60-0653-26 |
| 622-2224-201 | Collins 621A-6/6A ATC | 60-0653-26 |
| 622-2588-001 | Collins 618T-2/5 HF Comm | 60-0653-46 |
| 622-2588-002 | Collins 618T-2/5 HF Comm | 60-0653-46 |
| 622-2920-001 | Collins 860E-4 DME | 60-0653-38 |
| 622-2920-002 | Collins 860E-4 DME | 60-0653-38 |
| 622-2920-003 | Collins 860E-4 DME | 60-0653-38 |
| 622-2920-004 | Collins 860E-4 DME | 60-0653-38 |
| 622-2920-005 | Collins 860E-4 DME | 60-0653-38 |
| 622-2921-001 | Collins 860E-5 DME | 60-0653-27 |
| 622-2921-002 | Collins 860E-5 DME | 60-0653-27 |
| 622-2921-004 | Collins 860E-5 DME | 60-0653-27 |
| 622-2921-005 | Collins 860E-5 DME | 60-0653-27 |
| 622-2921-006 | Collins 860E-5 DME | 60-0653-27 |
| 622-3178-001 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 622-3178-002 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 622-3178-003 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 622-3178-005 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 622-3255-001 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3255-002 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3255-009 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3257-001 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|--------------------------------|----------------|
| 622-3257-003 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3257-004 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3257-005 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3257-006 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3257-008 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3257-012 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3257-101 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3259-005 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 622-3371-001 | Collins 628T-1 HF Comm | 60-0653-48 |
| 622-3371-004 | Collins 628T-1 HF Comm | 60-0653-48 |
| 622-3372-001 | Collins 628T-2/A HF Comm | 60-0649-93 |
| 622-3890-002 | Collins 860F-4 Radio Altimeter | 60-0653-57 |
| 622-3890-003 | Collins 860F-4 Radio Altimeter | 60-0653-57 |
| 622-3890-004 | Collins 860F-4 Radio Altimeter | 60-0653-57 |
| 622-3890-014 | Collins 860F-4 Radio Altimeter | 60-0653-57 |
| 622-3890-015 | Collins 860F-4 Radio Altimeter | 60-0653-57 |
| 622-4096-001 | Collins 346D-2B PA Amp | 60-0653-61 |
| 622-4096-002 | Collins 346D-2B PA Amp | 60-0653-61 |
| 622-4540-001 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-002 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-020 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-021 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-022 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-023 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-120 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-121 | Collins DME-700 DME | 60-0649-61 |
| 622-4540-122 | Collins DME-700 DME | 60-0649-61 |
| 622-4542-002 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-020 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-101 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-102 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-103 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-104 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-120 | Collins LRA-700 Radio Alt | 60-0649-68 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|-------------------------------|----------------|
| 622-4542-121 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-221 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-222 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-420 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4542-421 | Collins LRA-700 Radio Alt | 60-0649-68 |
| 622-4593-507 | Collins MCDP-701 MCDP | 60-0649-49 |
| 622-4593-508 | Collins MCDP-701 MCDP | 60-0649-49 |
| 622-4717-003 | Collins MCP-701 MCP | 60-0649-51 |
| 622-4717-004 | Collins MCP-701 MCP | 60-0649-51 |
| 622-5001-104 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-106 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-107 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-108 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-109 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-110 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-111 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-113 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5001-114 | Collins RDMI-743 RMI | 60-0649-87 |
| 622-5002-203 | Collins RMI-733 Radio Mag Ind | 60-0649-71 |
| 622-5002-205 | Collins RMI-733 Radio Mag Ind | 60-0649-71 |
| 622-5002-207 | Collins RMI-733 Radio Mag Ind | 60-0649-71 |
| 622-5219-001 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 622-5219-002 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 622-5219-003 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 622-5219-004 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 622-5219-005 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 622-5219-020 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 622-5219-120 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 622-5220-001 | Collins VOR-700/A VOR | 60-0649-55 |
| 622-5220-002 | Collins VOR-700/A VOR | 60-0649-55 |
| 622-5220-020 | Collins VOR-700/A VOR | 60-0649-55 |
| 622-5220-102 | Collins VOR-700/A VOR | 60-0649-55 |
| 622-5220-103 | Collins VOR-700/A VOR | 60-0649-55 |
| 622-5220-120 | Collins VOR-700/A VOR | 60-0649-55 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|--------------------------------|----------------|
| 622-5221-002 | Collins ILS-700/A ILS | 60-0649-56 |
| 622-5221-102 | Collins ILS-700/A ILS | 60-0649-56 |
| 622-5221-120 | Collins ILS-700/A ILS | 60-0649-56 |
| 622-5222-001 | Collins ADF-700 ADF Rcvr | 60-0649-38 |
| 622-5222-002 | Collins ADF-700 ADF Rcvr | 60-0649-38 |
| 622-5222-020 | Collins ADF-700 ADF Rcvr | 60-0649-38 |
| 622-5222-102 | Collins ADF-700 ADF Rcvr | 60-0649-38 |
| 622-5222-120 | Collins ADF-700 ADF Rcvr | 60-0649-38 |
| 622-5222-420 | Collins ADF-700 ADF Rcvr | 60-0649-38 |
| 622-5272-001 | Collins HFS-700 HF Comm | 60-0649-63 |
| 622-5272-003 | Collins HFS-700 HF Comm | 60-0649-63 |
| 622-5272-020 | Collins HFS-700 HF Comm | 60-0649-63 |
| 622-5272-023 | Collins HFS-700 HF Comm | 60-0649-63 |
| 622-5272-120 | Collins HFS-700 HF Comm | 60-0649-63 |
| 622-5377-001 | Collins 628T-2/A HF Comm | 60-0649-93 |
| 622-5446-001 | Collins TPR-710A ATC | 60-0653-39 |
| 622-5446-001 | Collins TPR-710A ATC | 60-0717-03 |
| 622-5446-002 | Collins TPR-710A ATC | 60-0717-03 |
| 622-5446-002 | Collins TPR-710A ATC | 60-0653-39 |
| 622-5446-101 | Collins TPR-710A ATC | 60-0717-03 |
| 622-5446-101 | Collins TPR-710A ATC | 60-0653-39 |
| 622-5446-102 | Collins TPR-710A ATC | 60-0717-03 |
| 622-5446-102 | Collins TPR-710A ATC | 60-0653-39 |
| 622-7382-101 | Collins ADF-462 ADF Rcvr | 60-0649-17 |
| 622-7878-200 | Collins TPR-720/TPR-900 Mode-S | 60-0649-67 |
| 622-7878-201 | Collins TPR-720/TPR-900 Mode-S | 60-0649-67 |
| 622-7878-301 | Collins TPR-720/TPR-900 Mode-S | 60-0649-67 |
| 622-7998-002 | Collins EDU-766D/776D EDU | 60-0649-39 |
| 622-7998-003 | Collins EDU-766D/776D EDU | 60-0649-39 |
| 622-7998-013 | Collins EDU-766D/776D EDU | 60-0649-39 |
| 622-7999-002 | Collins EDU-766D/776D EDU | 60-0649-39 |
| 622-7999-003 | Collins EDU-766D/776D EDU | 60-0649-39 |
| 622-7999-013 | Collins EDU-766D/776D EDU | 60-0649-39 |
| 622-8590-100 | Collins DCP-7000 Control Panel | 60-0649-79 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|--------------------------------|----------------|
| 622-8590-101 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-102 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-104 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-105 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-106 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-107 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-108 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-109 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-110 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-111 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-112 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8590-113 | Collins DCP-7000 Control Panel | 60-0649-79 |
| 622-8591-100 | Collins DSP-7000 Switch Panel | 60-0649-80 |
| 622-8757-104 | Collins FCC-702 FCC | 60-0649-62 |
| 622-8757-105 | Collins FCC-702 FCC | 60-0649-62 |
| 622-8757-106 | Collins FCC-702 FCC | 60-0649-62 |
| 622-8971-020 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-020 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-022 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-022 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-120 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-120 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-122 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-122 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-320 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-320 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-322 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-322 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-420 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-420 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-422 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-422 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-500 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-500 | Collins TTR-92x P/N Utility | 60-0649-94 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|---------------------------------------|----------------|
| 622-8971-522 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-522 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-620 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-620 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-8971-622 | Collins TTR-920 TCAS | 60-0649-50 |
| 622-8971-622 | Collins TTR-92x P/N Utility | 60-0649-94 |
| 622-9210-004 | Collins TDR-94D Mode-S | 60-0649-18 |
| 622-9436-100 | Collins EFIP-701E EFIP | 60-0649-24 |
| 622-9436-101 | Collins EFIP-701E EFIP | 60-0649-24 |
| 622-9738-020 | Collins ILS-720 ILS | 60-0649-57 |
| 622-9738-021 | Collins ILS-720 ILS | 60-0649-57 |
| 622-9738-040 | Collins ILS-720 ILS | 60-0649-57 |
| 622-9738-041 | Collins ILS-720 ILS | 60-0649-57 |
| 622-9738-220 | Collins ILS-720 ILS | 60-0649-57 |
| 622-9738-420 | Collins ILS-720 ILS | 60-0649-57 |
| 65-52818-14 | Boeing Autoslat Computer | 60-0653-19 |
| 65-52818-5 | Boeing Autoslat Computer | 60-0653-19 |
| 65-52818-7 | Boeing Autoslat Computer | 60-0653-19 |
| 65-52818-9 | Boeing Autoslat Computer | 60-0653-19 |
| 65-52819-13 | Boeing Digital Stall Warning Computer | 60-0653-17 |
| 65-52819-23 | Boeing Digital Stall Warning Computer | 60-0653-17 |
| 65-52819-25 | Boeing Digital Stall Warning Computer | 60-0653-17 |
| 65-52819-7 | Boeing Digital Stall Warning Computer | 60-0653-17 |
| 735SUE 6-10 | GE 735SUE Autothrottle | 60-0649-12 |
| 735SUE 6-9 | GE 735SUE Autothrottle | 60-0649-12 |
| 735SUE 8-10 | GE 735SUE Autothrottle | 60-0649-12 |
| 735SUE 8-9 | GE 735SUE Autothrottle | 60-0649-12 |
| 735SUE 9-11 | GE 735SUE Autothrottle | 60-0649-12 |
| 735SUE 9-12 | GE 735SUE Autothrottle | 60-0649-12 |
| 735SUE10-11 | GE 735SUE Autothrottle | 60-0649-12 |
| 735SUE10-12 | GE 735SUE Autothrottle | 60-0649-12 |
| 7517800-10001 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-10002 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-10003 | ACSS XS-950 Mode-S | 60-0649-74 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|--------------------|----------------|
| 7517800-10004 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-10005 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-10007 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-10009 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-10100 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-11006 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-11009 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-55001 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-55002 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-55003 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-55004 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-55005 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-55009 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-56006 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517800-56009 | ACSS XS-950 Mode-S | 60-0649-74 |
| 7517900-10001 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10002 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10003 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10004 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10006 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10007 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10010 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10011 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-10012 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55001 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55002 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55003 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55004 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55006 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55007 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55009 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55010 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55011 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-55012 | ACSS RT-950 TCAS | 60-0649-75 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|------------------------|----------------|
| 7517900-71002 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-71003 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-71004 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-71006 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-71007 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-71010 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-71011 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517900-71012 | ACSS RT-950 TCAS | 60-0649-75 |
| 7517905-61002 | ACSS RT-950 TCAS | 60-0649-75 |
| 755SUE 1-1 | GE 755SUE Autothrottle | 60-0649-13 |
| 755SUE 2-2 | GE 755SUE Autothrottle | 60-0649-13 |
| 755SUE 2-3 | GE 755SUE Autothrottle | 60-0649-13 |
| 755SUE 2-4 | GE 755SUE Autothrottle | 60-0649-13 |
| 760SUE1-1 | GE 760SUE Autothrottle | 60-0649-78 |
| 760SUE2-2 | GE 760SUE Autothrottle | 60-0649-78 |
| 760SUE2-3 | GE 760SUE Autothrottle | 60-0649-78 |
| 760SUE2-4 | GE 760SUE Autothrottle | 60-0649-78 |
| 777-1480-001 | Collins 51RV-2B VOR | 60-0653-22 |
| 777-1492-001 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 777-1492-002 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 777-1492-003 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 777-1492-004 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 777-1492-005 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 777-1492-006 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 787-6211-001 | Collins 621A-6/6A ATC | 60-0653-26 |
| 787-6211-002 | Collins 621A-6/6A ATC | 60-0653-26 |
| 787-6211-003 | Collins 621A-6/6A ATC | 60-0653-26 |
| 792-6021-002 | Collins ILS-70 ILS | 60-0653-65 |
| 792-6021-003 | Collins ILS-70 ILS | 60-0653-65 |
| 792-6021-004 | Collins ILS-70 ILS | 60-0653-65 |
| 792-6021-102 | Collins ILS-70 ILS | 60-0653-65 |
| 792-6021-103 | Collins ILS-70 ILS | 60-0653-65 |
| 792-6021-104 | Collins ILS-70 ILS | 60-0653-65 |
| 792-6216-001 | Collins 51Y-7/A/C ADF | 60-0653-36 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|---------------------------------|----------------|
| 792-6216-002 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 792-6216-003 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 792-6216-004 | Collins 51Y-7/A/C ADF | 60-0653-36 |
| 822-0101-002 | Collins HF9031 HF Comm | 60-0649-16 |
| 822-0195-100 | Collins MCP-770 MCP | 60-0649-95 |
| 822-0195-102 | Collins MCP-770 MCP | 60-0649-95 |
| 822-0282-002 | Collins ILS-700/A ILS | 60-0649-56 |
| 822-0282-102 | Collins ILS-700/A ILS | 60-0649-56 |
| 822-0282-120 | Collins ILS-700/A ILS | 60-0649-56 |
| 822-0297-001 | Collins VOR-900 VOR | 60-0649-73 |
| 822-0297-020 | Collins VOR-900 VOR | 60-0649-73 |
| 822-0297-220 | Collins VOR-900 VOR | 60-0649-73 |
| 822-0298-001 | Collins ILS-900 ILS | 60-0649-69 |
| 822-0298-020 | Collins ILS-900 ILS | 60-0649-69 |
| 822-0298-220 | Collins ILS-900 ILS | 60-0649-69 |
| 822-0299-001 | Collins ADF-900 ADF Rcvr | 60-0649-65 |
| 822-0299-020 | Collins ADF-900 ADF Rcvr | 60-0649-65 |
| 822-0299-021 | Collins ADF-900 ADF Rcvr | 60-0649-65 |
| 822-0299-220 | Collins ADF-900 ADF Rcvr | 60-0649-65 |
| 822-0323-002 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-0323-002 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-0323-020 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-0323-020 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-0323-220 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-0323-220 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-0329-001 | Collins DME-900 DME | 60-0649-44 |
| 822-0329-020 | Collins DME-900 DME | 60-0649-44 |
| 822-0329-021 | Collins DME-900 DME | 60-0649-44 |
| 822-0329-022 | Collins DME-900 DME | 60-0649-44 |
| 822-0329-220 | Collins DME-900 DME | 60-0649-44 |
| 822-0330-001 | Collins HFS-900 HF Comm | 60-0649-85 |
| 822-0330-020 | Collins HFS-900 HF Comm | 60-0649-85 |
| 822-0330-220 | Collins HFS-900 HF Comm | 60-0649-85 |
| 822-0334-002 | Collins LRA-900 Radio Altimeter | 60-0649-81 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|---------------------------------|----------------|
| 822-0334-020 | Collins LRA-900 Radio Altimeter | 60-0649-81 |
| 822-0334-220 | Collins LRA-900 Radio Altimeter | 60-0649-81 |
| 822-0334-221 | Collins LRA-900 Radio Altimeter | 60-0649-81 |
| 822-0336-001 | Collins TPR-720/TPR-900 Mode-S | 60-0649-67 |
| 822-0336-020 | Collins TPR-720/TPR-900 Mode-S | 60-0649-67 |
| 822-0336-220 | Collins TPR-720/TPR-900 Mode-S | 60-0649-67 |
| 822-0693-001 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 822-0693-002 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 822-0693-003 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 822-0693-004 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 822-0693-005 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 822-0693-020 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 822-0693-120 | Collins VHF-700/A VHF Comm | 60-0649-58 |
| 822-0726-002 | Collins VOR-700/A VOR | 60-0649-55 |
| 822-0726-020 | Collins VOR-700/A VOR | 60-0649-55 |
| 822-0726-103 | Collins VOR-700/A VOR | 60-0649-55 |
| 822-0726-120 | Collins VOR-700/A VOR | 60-0649-55 |
| 822-0760-001 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0760-002 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0760-009 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-001 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-003 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-004 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-005 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-006 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-008 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-012 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0761-101 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0762-002 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0762-005 | Collins 51RV-4/5 VOR/ILS | 60-0649-76 |
| 822-0990-001 | Collins HFS-900D HF Comm | 60-0649-92 |
| 822-0990-002 | Collins HFS-900D HF Comm | 60-0649-92 |
| 822-0990-003 | Collins HFS-900D HF Comm | 60-0649-92 |
| 822-0990-004 | Collins HFS-900D HF Comm | 60-0649-92 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------|----------------|
| 822-0990-020 | Collins HFS-900D HF Comm | 60-0649-92 |
| 822-1044-003 | Collins VHF-700B VHF Comm | 60-0649-59 |
| 822-1044-004 | Collins VHF-700B VHF Comm | 60-0649-59 |
| 822-1044-005 | Collins VHF-700B VHF Comm | 60-0649-59 |
| 822-1044-020 | Collins VHF-700B VHF Comm | 60-0649-59 |
| 822-1044-120 | Collins VHF-700B VHF Comm | 60-0649-59 |
| 822-1044-121 | Collins VHF-700B VHF Comm | 60-0649-59 |
| 822-1045-001 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-003 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-004 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-005 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-006 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-008 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-009 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-301 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-303 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-311 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-401 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-403 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-411 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-503 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-505 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-506 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-508 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1045-509 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-001 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-003 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-011 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-101 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-103 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-111 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-203 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-205 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-206 | Collins 618M-5/5A VHF Comm | 60-0653-34 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|----------------------------|----------------|
| 822-1046-208 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1046-209 | Collins 618M-5/5A VHF Comm | 60-0653-34 |
| 822-1047-002 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-1047-002 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-1047-003 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-1047-003 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-1047-010 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-1047-010 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-1047-020 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-1047-020 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-1047-030 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-1047-030 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-1047-220 | Collins VHF-900 Alignment | 60-0717-08 |
| 822-1047-220 | Collins VHF-900/900B Comm | 60-0649-45 |
| 822-1152-001 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-002 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-003 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-120 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-121 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-122 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-130 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-131 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1152-220 | Collins GLU-920 MMR | 60-0649-77 |
| 822-1236-001 | Collins GNLU-930 MMR | 60-0649-88 |
| 822-1293-001 | Collins TTR-921 TCAS | 60-0649-90 |
| 822-1293-002 | Collins TTR-921 TCAS | 60-0649-90 |
| 822-1293-220 | Collins TTR-921 TCAS | 60-0649-90 |
| 822-1293-320 | Collins TTR-921 TCAS | 60-0649-90 |
| 822-1293-321 | Collins TTR-921 TCAS | 60-0649-90 |
| 822-1338-001 | Collins TPR-901 Mode-S | 60-0649-89 |
| 822-1338-002 | Collins TPR-901 Mode-S | 60-0649-89 |
| 822-1338-003 | Collins TPR-901 Mode-S | 60-0649-89 |
| 822-1338-020 | Collins TPR-901 Mode-S | 60-0649-89 |
| 822-1338-021 | Collins TPR-901 Mode-S | 60-0649-89 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|---------------------------|----------------|
| 9599-607-14901 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14905 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14919 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14921 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14923 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14931 | Thales ERT-530A Radio Alt | 60-0649-42 |
| 9599-607-14932 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14939 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14940 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14941 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14942 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 9599-607-14943 | Thales ERT-530 Radio Alt | 60-0717-06 |
| 960-0329-008 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-009 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-010 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-011 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-012 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-015 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-016 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-017 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-018 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-019 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-020 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-021 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-022 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-023 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-024 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 960-0329-025 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 965-0476-088 | Honeywell GPWC Mk II | 60-0653-44 |
| 965-0648-003 | Honeywell GPWC Mk 5 | 60-0649-72 |
| 965-0648-004 | Honeywell GPWC Mk 5 | 60-0649-72 |
| 965-0648-005 | Honeywell GPWC Mk 5 | 60-0649-72 |
| 965-0648-008 | Honeywell GPWC Mk 5 | 60-0649-72 |
| 965-0648-009 | Honeywell GPWC Mk 5 | 60-0649-72 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|------------------------------------|----------------|
| 965-0648-011 | Honeywell GPWC Mk 5 | 60-0649-72 |
| 965-0676-020 | Honeywell GPWC Mk 5 | 60-0649-72 |
| 965-1690-050 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 965-1690-051 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| 965-1690-052 | Honeywell EGPWC Mk 5 | 60-0649-82 |
| CG1092AC01 | Honeywell CG1092AC IRMP | 60-1200-40 |
| CG1093AC01 | Honeywell CG1093 IRMP | 60-1200-18 |
| CG1093AD01 | Honeywell CG1093 IRMP | 60-1200-18 |
| CG1093AD02 | Honeywell CG1093 IRMP | 60-1200-18 |
| CG1093AD03 | Honeywell CG1093 IRMP | 60-1200-18 |
| CG1093AD10 | Honeywell CG1093 IRMP | 60-1200-18 |
| CG1135AC01 | Honeywell CG1135AC ISDU | 60-1200-34 |
| CG1135AC02 | Honeywell CG1135AC ISDU | 60-1200-34 |
| CG1135AC03 | Honeywell CG1135AC ISDU | 60-1200-34 |
| CG1135AC10 | Honeywell CG1135AC ISDU | 60-1200-34 |
| CG1136AC01 | Honeywell CG1136AC ISDU | 60-1200-25 |
| CG1137AC01 | Honeywell CG1137AC MSU | 60-1200-26 |
| CG1151AC03 | Honeywell CG1151AC CDU | 60-1200-20 |
| CG1234AC01 | Honeywell CG1234AC MSU | 60-1200-19 |
| CG1234AC02 | Honeywell CG1234AC MSU | 60-1200-19 |
| CG1237BD01 | Honeywell CG1237BD MSU | 60-1200-30 |
| CG1244AD01 | Honeywell CG1244AD MSU | 60-1200-31 |
| CG1244AD11 | Honeywell CG1244AD MSU | 60-1200-31 |
| D150000 | RA-NAV Marker Beacon | 60-0649-15 |
| DG1035AB03 | Honeywell DG1035AB03 DAA | 60-0649-26 |
| FMC2907A | GE 2907A FMC | 60-0653-54 |
| FMC2907A3 | GE 2907A FMC | 60-0653-54 |
| FMC2907A4 | GE 2907A FMC | 60-0653-54 |
| HG1050AC03 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AC03 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AC04 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AC04 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AC09 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AC09 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|---------------------------------------|----------------|
| HG1050AC10 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AC10 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AC11 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AC11 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD04 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD04 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD05 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD05 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD06 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD06 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD07 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD07 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD09 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD09 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD10 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD10 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD11 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD11 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AD12 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AD12 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AE09 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AE09 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AE10 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050AE10 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AE11 | Honeywell HG1050AX IRU (Semi-Auto) | 60-1200-09 |
| HG1050AE11 | Honeywell HG1050AX IRU (Automatic) | 60-1200-09 |
| HG1050BD02 | Honeywell HG1050BD02/05 IRU (Automati | 60-1200-23 |
| HG1050BD02 | Honeywell HG1050BD02/05 IRU (Semi-Aut | 60-1200-23 |
| HG1050BD05 | Honeywell HG1050BD02/05 IRU (Automati | 60-1200-23 |
| HG1050BD05 | Honeywell HG1050BD02/05 IRU (Semi-Aut | 60-1200-23 |
| HG1050BD06 | Honeywell HG1050BD02/05 IRU (Automati | 60-1200-23 |
| HG1050BD06 | Honeywell HG1050BD02/05 IRU (Semi-Aut | 60-1200-23 |
| HG1050BD07 | Honeywell HG1050BD02/05 IRU (Automati | 60-1200-23 |
| HG1050BD07 | Honeywell HG1050BD02/05 IRU (Semi-Aut | 60-1200-23 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|---------------------------------------|----------------|
| HG1050BD08 | Honeywell HG1050BD02/05 IRU (Automati | 60-1200-23 |
| HG1050BD08 | Honeywell HG1050BD02/05 IRU (Semi-Aut | 60-1200-23 |
| HG1050BD09 | Honeywell HG1050BD02/05 IRU (Automati | 60-1200-23 |
| HG1050BD09 | Honeywell HG1050BD02/05 IRU (Semi-Aut | 60-1200-23 |
| HG1103BA | Honeywell HG1103BA IRU (Semi-Auto) | 60-1200-35 |
| HG1103BA | Honeywell HG1103BA IRU (Automatic) | 60-1200-35 |
| HG1150AC05 | Honeywell HG1150AC ADIRU (Semi-Auto) | 60-1200-13 |
| HG1150AC05 | Honeywell HG1150AC ADIRU (Automatic) | 60-1200-13 |
| HG1150AC06 | Honeywell HG1150AC ADIRU (Automatic) | 60-1200-13 |
| HG1150AC06 | Honeywell HG1150AC ADIRU (Semi-Auto) | 60-1200-13 |
| HG1150AC07 | Honeywell HG1150AC ADIRU (Automatic) | 60-1200-13 |
| HG1150AC07 | Honeywell HG1150AC ADIRU (Semi-Auto) | 60-1200-13 |
| HG1150AC08 | Honeywell HG1150AC ADIRU (Automatic) | 60-1200-13 |
| HG1150AC08 | Honeywell HG1150AC ADIRU (Semi-Auto) | 60-1200-13 |
| HG1150BD02 | Honeywell HG1150BD IRU (Semi-Auto) | 60-1200-11 |
| HG1150BD02 | Honeywell HG1150BD IRU (Automatic) | 60-1200-11 |
| HG2001BC02 | Honeywell HG2001BC IRU (Semi-Auto) | 60-1200-32 |
| HG2001BC02 | Honeywell HG2001BC IRU (Automatic) | 60-1200-32 |
| HG2001BC03 | Honeywell HG2001BC IRU (Semi-Auto) | 60-1200-32 |
| HG2001BC03 | Honeywell HG2001BC IRU (Automatic) | 60-1200-32 |
| HG2030AC06 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AC06 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AC08 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AC08 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AC09 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AC09 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AC11 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AC11 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AC13 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AC13 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AD09 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AD09 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AD10 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AD10 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|---|----------------|
| HG2030AD11 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AD11 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AD12 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AD12 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AE20 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AE20 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AE21 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AE21 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AE22 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030AE22 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AE23 | Honeywell HG2030 ADIRU (Semi-Auto) | 60-1200-22 |
| HG2030AE23 | Honeywell HG2030 ADIRU (Automatic) | 60-1200-22 |
| HG2030xx | Honeywell HG2030 Level II GPS/ADIRU | 60-1200-41 |
| HG2040AD01 | Honeywell HG2040 SAARU | 60-1200-15 |
| HG2040AD02 | Honeywell HG2040 SAARU | 60-1200-15 |
| HG2040xx | Honeywell HG2040 Level II SAARU | 60-1200-28 |
| HG2050AC01 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC01 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050AC02 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050AC02 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC03 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050AC03 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC04 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050AC04 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC05 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050AC05 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC06 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050AC06 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC07 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC07 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050AC50 | Honeywell HG2050AC ADIRU (Semi-Auto) | 60-1200-38 |
| HG2050AC50 | Honeywell HG2050AC ADIRU (Automatic) | 60-1200-38 |
| HG2050xx | Honeywell HG2050 Limited Level II ADIRU | 60-1200-44 |
| HG2060AC02 | Honeywell HG2060 FTADIRU | 60-1200-17 |

| LRU Part Number | LRU Name | TPS P/N |
|------------------------|--------------------------|----------------|
| HG2060AD01 | Honeywell HG2060 FTADIRU | 60-1200-17 |
| HG480B40 | Honeywell HG480B DADC | 60-0649-66 |
| HG480B41 | Honeywell HG480B DADC | 60-0649-66 |
| HG480B42 | Honeywell HG480B DADC | 60-0649-66 |
| TLS755-01-0100A | Thales TLS-755 MMR | 60-0649-43 |
| TLS755-01-0101B | Thales TLS-755 MMR | 60-0649-43 |
| TLS755-01-0102A | Thales TLS-755 MMR | 60-0649-43 |

LRUs Tested Sorted By LRU Name

| LRU Name | LRU Part Number | TPS P/N |
|--------------------------------------|------------------------|----------------|
| Aeroflex TPS Utility for TPA-81A | 066-50000-0108 | 60-0649-99 |
| Honeywell RNA-34AF VOR | 3614306-3402 | 60-0649-19 |
| Honeywell RNA-34AF VOR | 3614306-3401 | 60-0649-19 |
| Honeywell DMA-37A DME | 2041167-3701 | 60-0649-20 |
| Honeywell DMA-37A DME | 2041167-3707 | 60-0649-20 |
| Honeywell DMA-37A DME | 2041167-3703 | 60-0649-20 |
| Honeywell DMA-37A DME | 2041167-3706 | 60-0649-20 |
| Honeywell DMA-37A DME | 2041167-3702 | 60-0649-20 |
| Honeywell DMA-37A DME | 2041167-3709 | 60-0649-20 |
| Honeywell DMA-37A DME | 2041167-3705 | 60-0649-20 |
| Honeywell DMA-37A DME | 2041167-3704 | 60-0649-20 |
| Honeywell CG1244AD MSU | CG1244AD11 | 60-1200-31 |
| Honeywell CG1244AD MSU | CG1244AD01 | 60-1200-31 |
| Honeywell HG2001BC IRU (Semi-Auto) | HG2001BC02 | 60-1200-32 |
| Honeywell HG2001BC IRU (Semi-Auto) | HG2001BC03 | 60-1200-32 |
| Honeywell CG1135AC ISDU | CG1135AC01 | 60-1200-34 |
| Honeywell CG1135AC ISDU | CG1135AC10 | 60-1200-34 |
| Honeywell CG1135AC ISDU | CG1135AC03 | 60-1200-34 |
| Honeywell CG1135AC ISDU | CG1135AC02 | 60-1200-34 |
| Honeywell HG1103BA IRU (Semi-Auto) | HG1103BA | 60-1200-35 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC01 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC06 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC05 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC04 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC03 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC02 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC07 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Semi-Auto) | HG2050AC50 | 60-1200-38 |
| Honeywell KTR909B UHF Comm | 064-01076-0101 | 60-0649-22 |
| Honeywell Cabin Pressure Controller | 2117388-06 | 60-0649-25 |
| Honeywell Cabin Pressure Controller | 2117388-08 | 60-0649-25 |
| Honeywell Cabin Pressure Controller | 2117388-10 | 60-0649-25 |

| LRU Name | LRU Part Number | TPS P/N |
|-------------------------------------|------------------------|----------------|
| Honeywell Cabin Pressure Controller | 2117388-11 | 60-0649-25 |
| Honeywell Cabin Pressure Controller | 2117388-05 | 60-0649-25 |
| Honeywell Cabin Pressure Controller | 2117388-07 | 60-0649-25 |
| Honeywell DG1035AB03 DAA | DG1035AB03 | 60-0649-26 |
| Honeywell RIA-35B ILS | 066-50006-1202 | 60-0649-27 |
| Honeywell RIA-35B ILS | 066-50006-0101 | 60-0649-27 |
| Honeywell RIA-35B ILS | 066-50006-1101 | 60-0649-27 |
| Honeywell RIA-35B ILS | 066-50006-0202 | 60-0649-27 |
| Honeywell RVA-36B VOR | 066-50012-0101 | 60-0649-28 |
| Honeywell RVA-36B VOR | 066-50012-0212 | 60-0649-28 |
| Honeywell RVA-36B VOR | 066-50012-0202 | 60-0649-28 |
| Honeywell RVA-36B VOR | 066-50012-0303 | 60-0649-28 |
| Honeywell DFA-75B ADF Rcvr | 066-50014-0101 | 60-0649-29 |
| Honeywell DFA-75B ADF Rcvr | 066-50014-0202 | 60-0649-29 |
| Honeywell RIA-35B Align | 066-50006-0202 | 60-0649-2A |
| Honeywell RIA-35B Align | 066-50006-0101 | 60-0649-2A |
| Honeywell RVA-36B Align | 066-50012-0101 | 60-0649-2B |
| Honeywell RVA-36B Align | 066-50012-0202 | 60-0649-2B |
| Honeywell DFA-75B Align | 066-50014-0101 | 60-0649-2C |
| Honeywell DFA-75B Align | 066-50014-0202 | 60-0649-2C |
| Honeywell RTA-44D VHF Comm | 064-50000-0303 | 60-0649-30 |
| Honeywell RTA-44D VHF Comm | 064-50000-0101 | 60-0649-30 |
| Honeywell RTA-44D VHF Comm | 064-50000-0202 | 60-0649-30 |
| Honeywell RTA-83A VHF Comm | 064-50001-0101 | 60-0649-31 |
| Honeywell TPA-81A TCAS | 066-50000-0607 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0708 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0606 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0507 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0504 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0408 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1408 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2321 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0608 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1911 | 60-0649-35 |

| LRU Name | LRU Part Number | TPS P/N |
|------------------------|------------------------|----------------|
| Honeywell TPA-81A TCAS | 066-50000-0407 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0405 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0102 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0308 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0302 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2720 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0301 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0109 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0203 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0208 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0910 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2320 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0107 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0402 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1108 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0508 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2620 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0207 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2721 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2930 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2220 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2121 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2120 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1208 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0108 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2221 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1910 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0808 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-0307 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-2621 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1109 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1508 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1608 | 60-0649-35 |
| Honeywell TPA-81A TCAS | 066-50000-1708 | 60-0649-35 |

| LRU Name | LRU Part Number | TPS P/N |
|------------------------------|------------------------|----------------|
| Honeywell TRA-67A ATC/Mode-S | 066-01127-1602 | 60-0649-36 |
| Honeywell TRA-67A ATC/Mode-S | 066-01127-0000 | 60-0649-36 |
| Honeywell TRA-67A ATC/Mode-S | 066-01127-1101 | 60-0649-36 |
| Honeywell TRA-67A ATC/Mode-S | 066-01127-1402 | 60-0649-36 |
| Honeywell TRA-67A ATC/Mode-S | 066-01127-1601 | 60-0649-36 |
| Honeywell TRA-67A ATC/Mode-S | 066-01127-1401 | 60-0649-36 |
| Honeywell TRA-67A ATC/Mode-S | 066-01127-1301 | 60-0649-36 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3520 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3518 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3517 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3504 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3515 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3503 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3523 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3521 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3516 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3527 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3522 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3519 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3514 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3530 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3531 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3532 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3526 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3525 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3528 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3529 | 60-0649-46 |
| Honeywell RIA-35A ILS Rcvr | 2041230-3533 | 60-0649-46 |
| Honeywell RVA-36A VOR/MB | 2041231-3613 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3623 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3616 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3617 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3610 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3614 | 60-0649-47 |

| LRU Name | LRU Part Number | TPS P/N |
|----------------------------|------------------------|----------------|
| Honeywell RVA-36A VOR/MB | 2041231-3615 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3601 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3604 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3622 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3608 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3607 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3606 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3611 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3609 | 60-0649-47 |
| Honeywell RVA-36A VOR/MB | 2041231-3618 | 60-0649-47 |
| Honeywell RTA-44A VHF Comm | 2041237-4433 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4418 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4432 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4413 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4406 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4424 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4407 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4408 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4422 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4412 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4410 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4425 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4426 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4429 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4430 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4431 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4401 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4411 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4417 | 60-0649-52 |
| Honeywell RTA-44A VHF Comm | 2041237-4428 | 60-0649-52 |
| Honeywell DFA-75A ADF Rcvr | 2041168-7511 | 60-0649-60 |
| Honeywell DFA-75A ADF Rcvr | 2041168-7513 | 60-0649-60 |
| Honeywell DFA-75A ADF Rcvr | 2041168-7510 | 60-0649-60 |
| Honeywell DFA-75A ADF Rcvr | 2041168-7512 | 60-0649-60 |

| LRU Name | LRU Part Number | TPS P/N |
|----------------------------|------------------------|----------------|
| Honeywell DFA-75A ADF Rcvr | 2041168-7514 | 60-0649-60 |
| Honeywell DFA-75A ADF Rcvr | 2041168-7501 | 60-0649-60 |
| Honeywell DFA-75A ADF Rcvr | 2041168-7506 | 60-0649-60 |
| Honeywell HG480B DADC | HG480B40 | 60-0649-66 |
| Honeywell HG480B DADC | HG480B41 | 60-0649-66 |
| Honeywell HG480B DADC | HG480B42 | 60-0649-66 |
| Honeywell GPWC Mk 5 | 965-0648-004 | 60-0649-72 |
| Honeywell GPWC Mk 5 | 965-0648-008 | 60-0649-72 |
| Honeywell GPWC Mk 5 | 965-0648-005 | 60-0649-72 |
| Honeywell GPWC Mk 5 | 965-0648-011 | 60-0649-72 |
| Honeywell GPWC Mk 5 | 965-0648-009 | 60-0649-72 |
| Honeywell GPWC Mk 5 | 965-0648-003 | 60-0649-72 |
| Honeywell GPWC Mk 5 | 965-0676-020 | 60-0649-72 |
| Honeywell EGPWC Mk 5 | 960-0329-017 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 965-1690-050 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 965-1690-052 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-011 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-020 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-012 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-016 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 965-1690-051 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-018 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-021 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-010 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-019 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-025 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-015 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-024 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-009 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-022 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-023 | 60-0649-82 |
| Honeywell EGPWC Mk 5 | 960-0329-008 | 60-0649-82 |
| Honeywell HG480E DADC | 4061100-901 | 60-0717-01 |
| Honeywell KDM-7000B DME | 066-1019-X5 | 60-0653-13 |

| LRU Name | LRU Part Number | TPS P/N |
|------------------------------|------------------------|----------------|
| Honeywell KDM-7000B DME | 066-1019-X6 | 60-0653-13 |
| Honeywell KDM-7000B DME | 066-1019-X2 | 60-0653-13 |
| Honeywell KDM-7000B DME | 066-1019-63 | 60-0653-13 |
| Honeywell KDM-7000B DME | 066-1019-57 | 60-0653-13 |
| Honeywell KDM-7000B DME | 066-1019-55 | 60-0653-13 |
| Honeywell KDM-7000B DME | 066-1019-27 | 60-0653-13 |
| Honeywell KDM-7000B DME | 066-1019-X1 | 60-0653-13 |
| Honeywell KDM-7000B DME | 066-1019-23 | 60-0653-13 |
| Honeywell KDM-7070 DME | 066-1094-02 | 60-0653-14 |
| Honeywell KDM-7070 DME | 066-1094-03 | 60-0653-14 |
| Honeywell KDM-7070 DME | 066-1094-01 | 60-0653-14 |
| Honeywell KDM-7000B 521D DME | 066-3057-14 | 60-0653-15 |
| Honeywell KDM-7000B 521D DME | 066-3057-10 | 60-0653-15 |
| Honeywell KDM-7000B 521D DME | 066-3057-11 | 60-0653-15 |
| Honeywell KDM-7000B 521D DME | 066-3057-13 | 60-0653-15 |
| Honeywell KDM-7000B 521D DME | 066-3057-15 | 60-0653-15 |
| Honeywell KDM-7000B 521D DME | 066-3057-16 | 60-0653-15 |
| Honeywell KDM-7000B 521D DME | 066-3057-17 | 60-0653-15 |
| Honeywell KDM-7000B 521D DME | 066-3057-12 | 60-0653-15 |
| Honeywell KDM-7060 DME | 066-1093-20 | 60-0653-16 |
| Honeywell KDM-7060 DME | 066-1093-02 | 60-0653-16 |
| Honeywell KDM-7060 DME | 066-1093-00 | 60-0653-16 |
| Honeywell KDM-7060 DME | 066-1093-30 | 60-0653-16 |
| Honeywell KDM-7060 DME | 066-1093-10 | 60-0653-16 |
| Honeywell KDM-7060 DME | 066-1093-11 | 60-0653-16 |
| Honeywell KNR-6030 VOR | 066-1060-48 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 1149-00-50 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 1149-00-48 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 1149-00-18 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 1149-00-13 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 066-1060-01 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 1149-00-12 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 1149-00-04 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 1149-00-01 | 60-0653-18 |

| LRU Name | LRU Part Number | TPS P/N |
|------------------------------|------------------------|----------------|
| Honeywell KNR-6030 VOR | 066-1060-50 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 066-1060-12 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 066-1060-13 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 066-1060-18 | 60-0653-18 |
| Honeywell KNR-6030 VOR | 066-1060-04 | 60-0653-18 |
| Honeywell RNA-34A VOR/ILS | 2041234-3418 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3419 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3407 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3432 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3442 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3445 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3446 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3415 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3412 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3409 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3408 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3401 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3434 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3426 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3433 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3421 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3440 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3437 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3443 | 60-0653-23 |
| Honeywell RNA-34A VOR/ILS | 2041234-3422 | 60-0653-23 |
| Honeywell KTR-9100A VHF Comm | 064-1005-14 | 60-0653-24 |
| Honeywell KTR-9100A VHF Comm | 064-1005-12 | 60-0653-24 |
| Honeywell KTR-9100A VHF Comm | 064-1005-04 | 60-0653-24 |
| Honeywell KTR-9100A VHF Comm | 064-1005-02 | 60-0653-24 |
| Honeywell KTR-9100A VHF Comm | 064-1005-15 | 60-0653-24 |
| Honeywell KTR-9100A VHF Comm | 064-1005-03 | 60-0653-24 |
| Honeywell 4051601-9xx MCP | 4051601-940 | 60-0653-28 |
| Honeywell 4051601-9xx MCP | 4051601-938 | 60-0653-28 |
| Honeywell 4051601-9xx MCP | 4051601-935 | 60-0653-28 |

| LRU Name | LRU Part Number | TPS P/N |
|-----------------------------|------------------------|----------------|
| Honeywell 4051601-9xx MCP | 4051601-932 | 60-0653-28 |
| Honeywell 4051601-9xx MCP | 4051601-945 | 60-0653-28 |
| Honeywell KTR-9000 VHF Comm | 064-1004-00 | 60-0653-29 |
| Honeywell RTA-43A VHF Comm | 2070945-4311 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4315 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4321 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4305 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4325 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4332 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4335 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4322 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4331 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4312 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4301 | 60-0653-30 |
| Honeywell RTA-43A VHF Comm | 2070945-4302 | 60-0653-30 |
| Honeywell KXP-7500 ATC | 066-1056-00 | 60-0653-31 |
| Honeywell KXP-7500 ATC | 066-1056-01 | 60-0653-31 |
| Honeywell SP-300 FCC | 4051600-913 | 60-0717-07 |
| Honeywell SP-300 FCC | 4051600-914 | 60-0717-07 |
| Honeywell SP-300 FCC | 4051600-914 | 60-0653-32 |
| Honeywell SP-300 FCC | 4051600-912 | 60-0653-32 |
| Honeywell SP-300 FCC | 4051600-913 | 60-0653-32 |
| Honeywell SP-300 FCC | 4051600-923 | 60-0717-07 |
| Honeywell SP-300 FCC | 4051600-912 | 60-0717-07 |
| Honeywell RIA-32A ILS Rcvr | 2070724-3205 | 60-0653-33 |
| Honeywell RIA-32A ILS Rcvr | 2070724-3206 | 60-0653-33 |
| Honeywell RIA-32A ILS Rcvr | 2070724-3203 | 60-0653-33 |
| Honeywell RIA-32A ILS Rcvr | 2070724-3201 | 60-0653-33 |
| Honeywell RVA-33A VOR Rcvr | 2070750-3305 | 60-0653-41 |
| Honeywell RVA-33A VOR Rcvr | 2070750-3306 | 60-0653-41 |
| Honeywell RVA-33A VOR Rcvr | 2070750-3307 | 60-0653-41 |
| Honeywell RVA-33A VOR Rcvr | 2070750-3301 | 60-0653-41 |
| Honeywell GPWC Mk II | 965-0476-088 | 60-0653-44 |
| Honeywell 4051601-937 MCP | 4051601-937 | 60-0653-50 |

| LRU Name | LRU Part Number | TPS P/N |
|--------------------------------------|------------------------|----------------|
| Honeywell HG480E DADC | 4061100-901 | 60-0653-55 |
| Honeywell ARN-123 VOR | 4000937-6201 | 60-0653-56 |
| Honeywell ARN-123 VOR | 4000937-6221 | 60-0653-56 |
| Honeywell ARN-123 VOR | 4000937-6222 | 60-0653-56 |
| Honeywell ARN-123 VOR | 4000937-6202 | 60-0653-56 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD10 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AE11 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AE09 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AE10 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD05 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD04 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AC09 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD12 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD09 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AC03 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AC04 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD11 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD06 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AC11 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AC10 | 60-1200-09 |
| Honeywell HG1050AX IRU (Semi-Auto) | HG1050AD07 | 60-1200-09 |
| Honeywell HG1150BD IRU (Semi-Auto) | HG1150BD02 | 60-1200-11 |
| Honeywell HG1150AC ADIRU (Semi-Auto) | HG1150AC06 | 60-1200-13 |
| Honeywell HG1150AC ADIRU (Semi-Auto) | HG1150AC07 | 60-1200-13 |
| Honeywell HG1150AC ADIRU (Semi-Auto) | HG1150AC05 | 60-1200-13 |
| Honeywell HG1150AC ADIRU (Semi-Auto) | HG1150AC08 | 60-1200-13 |
| Honeywell HG2040 SAARU | HG2040AD01 | 60-1200-15 |
| Honeywell HG2040 SAARU | HG2040AD02 | 60-1200-15 |
| Honeywell HG2060 FTADIRU | HG2060AD01 | 60-1200-17 |
| Honeywell HG2060 FTADIRU | HG2060AC02 | 60-1200-17 |
| Honeywell CG1093 IRMP | CG1093AD10 | 60-1200-18 |
| Honeywell CG1093 IRMP | CG1093AD01 | 60-1200-18 |
| Honeywell CG1093 IRMP | CG1093AD03 | 60-1200-18 |
| Honeywell CG1093 IRMP | CG1093AD02 | 60-1200-18 |

| LRU Name | LRU Part Number | TPS P/N |
|---|------------------------|----------------|
| Honeywell CG1093 IRMP | CG1093AC01 | 60-1200-18 |
| Honeywell CG1234AC MSU | CG1234AC02 | 60-1200-19 |
| Honeywell CG1234AC MSU | CG1234AC01 | 60-1200-19 |
| Honeywell CG1151AC CDU | CG1151AC03 | 60-1200-20 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AC08 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AC09 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AE23 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AC06 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AE22 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AC11 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AE20 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AD12 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AD11 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AC13 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AD09 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AD10 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Semi-Auto) | HG2030AE21 | 60-1200-22 |
| Honeywell HG1050BD02/05 IRU (Semi-Auto) | HG1050BD05 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Semi-Auto) | HG1050BD02 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Semi-Auto) | HG1050BD06 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Semi-Auto) | HG1050BD07 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Semi-Auto) | HG1050BD08 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Semi-Auto) | HG1050BD09 | 60-1200-23 |
| Honeywell CG1136AC ISDU | CG1136AC01 | 60-1200-25 |
| Honeywell CG1137AC MSU | CG1137AC01 | 60-1200-26 |
| Honeywell HG2040 Level II SAARU | HG2040xx | 60-1200-28 |
| Honeywell CG1237BD MSU | CG1237BD01 | 60-1200-30 |
| Honeywell CG1092AC IRMP | CG1092AC01 | 60-1200-40 |
| Honeywell HG2030 Level II GPS/ADIRU | HG2030xx | 60-1200-41 |
| Honeywell HG2050 Limited Level II ADIRU | HG2050xx | 60-1200-44 |
| GE 735SUE Autothrottle | 735SUE 6-10 | 60-0649-12 |
| GE 735SUE Autothrottle | 735SUE 6-9 | 60-0649-12 |
| GE 735SUE Autothrottle | 735SUE10-12 | 60-0649-12 |
| GE 735SUE Autothrottle | 735SUE10-11 | 60-0649-12 |

| LRU Name | LRU Part Number | TPS P/N |
|------------------------|------------------------|----------------|
| GE 735SUE Autothrottle | 735SUE 9-11 | 60-0649-12 |
| GE 735SUE Autothrottle | 735SUE 8-9 | 60-0649-12 |
| GE 735SUE Autothrottle | 735SUE 8-10 | 60-0649-12 |
| GE 735SUE Autothrottle | 735SUE 9-12 | 60-0649-12 |
| GE 755SUE Autothrottle | 755SUE 1-1 | 60-0649-13 |
| GE 755SUE Autothrottle | 755SUE 2-4 | 60-0649-13 |
| GE 755SUE Autothrottle | 755SUE 2-3 | 60-0649-13 |
| GE 755SUE Autothrottle | 755SUE 2-2 | 60-0649-13 |
| GE 2577B/D/F CDU | 167550-02-01 | 60-0649-37 |
| GE 2577B/D/F CDU | 170089-02-01 | 60-0649-37 |
| GE 2577B/D/F CDU | 166891-01-01 | 60-0649-37 |
| GE 2577B/D/F CDU | 167550-01-01 | 60-0649-37 |
| GE 2577B/D/F CDU | 170089-01-01 | 60-0649-37 |
| GE 2904 FMC | 168925-13-01 | 60-0649-48 |
| GE 2904 FMC | 167726-11-01 | 60-0649-48 |
| GE 2904 FMC | 167726-08-01 | 60-0649-48 |
| GE 2904 FMC | 166805-06-01 | 60-0649-48 |
| GE 2904 FMC | 166805-08-01 | 60-0649-48 |
| GE 2904 FMC | 167726-18-01 | 60-0649-48 |
| GE 2904 FMC | 167726-17-01 | 60-0649-48 |
| GE 2904 FMC | 166805-11-01 | 60-0649-48 |
| GE 2904 FMC | 166805-09-01 | 60-0649-48 |
| GE 2904 FMC | 166805-07-01 | 60-0649-48 |
| GE 2904 FMC | 167726-15-01 | 60-0649-48 |
| GE 2904 FMC | 167726-21-01 | 60-0649-48 |
| GE 2904 FMC | 167726-05-01 | 60-0649-48 |
| GE 2904 FMC | 168925-10-01 | 60-0649-48 |
| GE 2904 FMC | 168925-14-01 | 60-0649-48 |
| GE 2904 FMC | 168925-12-01 | 60-0649-48 |
| GE 2904 FMC | 168925-15-01 | 60-0649-48 |
| GE 2904 FMC | 168925-11-01 | 60-0649-48 |
| GE 2904 FMC | 168925-16-01 | 60-0649-48 |
| GE 2904 FMC | 167726-04-01 | 60-0649-48 |
| GE 2904 FMC | 166805-13-01 | 60-0649-48 |

| LRU Name | LRU Part Number | TPS P/N |
|------------------------|------------------------|----------------|
| GE 2904 FMC | 168925-02-01 | 60-0649-48 |
| GE 2904 FMC | 167726-19-01 | 60-0649-48 |
| GE 2904 FMC | 166805-10-01 | 60-0649-48 |
| GE 2904 FMC | 168925-09-01 | 60-0649-48 |
| GE 2904 FMC | 166805-03-01 | 60-0649-48 |
| GE 2904 FMC | 167726-06-01 | 60-0649-48 |
| GE 2904 FMC | 166805-04-01 | 60-0649-48 |
| GE 2904 FMC | 167726-22-01 | 60-0649-48 |
| GE 2904 FMC | 167726-09-01 | 60-0649-48 |
| GE 2904 FMC | 168925-08-01 | 60-0649-48 |
| GE 2904 FMC | 167726-13-01 | 60-0649-48 |
| GE 2904 FMC | 167726-03-01 | 60-0649-48 |
| GE 2904 FMC | 168925-05-01 | 60-0649-48 |
| GE 2904 FMC | 166805-14-01 | 60-0649-48 |
| GE 2904 FMC | 167726-20-01 | 60-0649-48 |
| GE 2904 FMC | 167726-16-01 | 60-0649-48 |
| GE 2904 FMC | 167726-23-01 | 60-0649-48 |
| GE 2904 FMC | 167726-10-01 | 60-0649-48 |
| GE 2904 FMC | 167726-24-01 | 60-0649-48 |
| GE 2904 FMC | 166805-12-01 | 60-0649-48 |
| GE 2904 FMC | 167726-14-01 | 60-0649-48 |
| GE 2904 FMC | 166805-05-01 | 60-0649-48 |
| GE 2904 FMC | 167726-07-01 | 60-0649-48 |
| GE 2904 FMC | 168925-07-01 | 60-0649-48 |
| GE 2904 FMC | 168925-03-01 | 60-0649-48 |
| GE 2904 FMC | 168925-04-01 | 60-0649-48 |
| GE 2904 FMC | 168925-06-01 | 60-0649-48 |
| GE 760SUE Autothrottle | 760SUE1-1 | 60-0649-78 |
| GE 760SUE Autothrottle | 760SUE2-2 | 60-0649-78 |
| GE 760SUE Autothrottle | 760SUE2-3 | 60-0649-78 |
| GE 760SUE Autothrottle | 760SUE2-4 | 60-0649-78 |
| GE 2584 LCD CDU | 174101-01-01 | 60-0649-96 |
| GE 2584 LCD CDU | 174101-02-02 | 60-0649-96 |
| GE 2584 LCD CDU | 174101-02-03 | 60-0649-96 |

| LRU Name | LRU Part Number | TPS P/N |
|-----------------------------|------------------------|----------------|
| GE 2584 LCD CDU | 174101-01-02 | 60-0649-96 |
| GE 2584 LCD CDU | 174101-01-03 | 60-0649-96 |
| GE 2584 LCD CDU | 174101-03-01 | 60-0649-96 |
| GE 2584 LCD CDU | 174101-02-01 | 60-0649-96 |
| GE 2584 LCD CDU | 174101-03-02 | 60-0649-96 |
| GE 2584 LCD CDU | 174101-03-03 | 60-0649-96 |
| GE 2907C FMC | 176200-01-01 | 60-0649-97 |
| GE 2907A FMC | 171497-05-01 | 60-0717-02 |
| GE 2907A FMC | 171497-01-01 | 60-0717-02 |
| GE 2907A FMC | FMC2907A3 | 60-0653-54 |
| GE 2907A FMC | 171497-04-01 | 60-0717-02 |
| GE 2907A FMC | FMC2907A | 60-0653-54 |
| GE 2907A FMC | FMC2907A4 | 60-0653-54 |
| RA-NAV Marker Beacon | D150000 | 60-0649-15 |
| Collins HF9031 HF Comm | 822-0101-002 | 60-0649-16 |
| Collins ADF-462 ADF Rcvr | 622-7382-101 | 60-0649-17 |
| Collins TDR-94D Mode-S | 622-9210-004 | 60-0649-18 |
| Collins EFIP-701E EFIP | 622-9436-101 | 60-0649-24 |
| Collins EFIP-701E EFIP | 622-9436-100 | 60-0649-24 |
| Collins ADF-700 ADF Rcvr | 622-5222-001 | 60-0649-38 |
| Collins ADF-700 ADF Rcvr | 622-5222-420 | 60-0649-38 |
| Collins ADF-700 ADF Rcvr | 622-5222-102 | 60-0649-38 |
| Collins ADF-700 ADF Rcvr | 622-5222-020 | 60-0649-38 |
| Collins ADF-700 ADF Rcvr | 622-5222-002 | 60-0649-38 |
| Collins ADF-700 ADF Rcvr | 622-5222-120 | 60-0649-38 |
| Collins EDU-766D/776D EDU | 622-7998-002 | 60-0649-39 |
| Collins EDU-766D/776D EDU | 622-7998-013 | 60-0649-39 |
| Collins EDU-766D/776D EDU | 622-7998-003 | 60-0649-39 |
| Collins EDU-766D/776D EDU | 622-7999-002 | 60-0649-39 |
| Collins EDU-766D/776D EDU | 622-7999-013 | 60-0649-39 |
| Collins EDU-766D/776D EDU | 622-7999-003 | 60-0649-39 |
| Honeywell RTA-44D Alignment | 064-50000-0202 | 60-0649-3A |
| Honeywell RTA-44D Alignment | 064-50000-0101 | 60-0649-3A |
| Collins DME-900 DME | 822-0329-020 | 60-0649-44 |

| LRU Name | LRU Part Number | TPS P/N |
|---------------------------|------------------------|----------------|
| Collins DME-900 DME | 822-0329-001 | 60-0649-44 |
| Collins DME-900 DME | 822-0329-021 | 60-0649-44 |
| Collins DME-900 DME | 822-0329-220 | 60-0649-44 |
| Collins DME-900 DME | 822-0329-022 | 60-0649-44 |
| Collins VHF-900/900B Comm | 822-1047-030 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-1047-220 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-0323-220 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-1047-020 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-1047-010 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-1047-003 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-1047-002 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-0323-020 | 60-0649-45 |
| Collins VHF-900/900B Comm | 822-0323-002 | 60-0649-45 |
| Collins MCDP-701 MCDP | 622-4593-507 | 60-0649-49 |
| Collins MCDP-701 MCDP | 622-4593-508 | 60-0649-49 |
| Collins TTR-920 TCAS | 622-8971-620 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-020 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-500 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-422 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-322 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-320 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-122 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-120 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-420 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-022 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-522 | 60-0649-50 |
| Collins TTR-920 TCAS | 622-8971-622 | 60-0649-50 |
| Collins MCP-701 MCP | 622-4717-004 | 60-0649-51 |
| Collins MCP-701 MCP | 622-4717-003 | 60-0649-51 |
| Collins VOR-700/A VOR | 622-5220-103 | 60-0649-55 |
| Collins VOR-700/A VOR | 622-5220-001 | 60-0649-55 |
| Collins VOR-700/A VOR | 822-0726-020 | 60-0649-55 |
| Collins VOR-700/A VOR | 622-5220-020 | 60-0649-55 |
| Collins VOR-700/A VOR | 622-5220-120 | 60-0649-55 |

| LRU Name | LRU Part Number | TPS P/N |
|----------------------------|------------------------|----------------|
| Collins VOR-700/A VOR | 822-0726-103 | 60-0649-55 |
| Collins VOR-700/A VOR | 822-0726-120 | 60-0649-55 |
| Collins VOR-700/A VOR | 822-0726-002 | 60-0649-55 |
| Collins VOR-700/A VOR | 622-5220-102 | 60-0649-55 |
| Collins VOR-700/A VOR | 622-5220-002 | 60-0649-55 |
| Collins ILS-700/A ILS | 822-0282-120 | 60-0649-56 |
| Collins ILS-700/A ILS | 622-5221-102 | 60-0649-56 |
| Collins ILS-700/A ILS | 622-5221-120 | 60-0649-56 |
| Collins ILS-700/A ILS | 822-0282-002 | 60-0649-56 |
| Collins ILS-700/A ILS | 822-0282-102 | 60-0649-56 |
| Collins ILS-700/A ILS | 622-5221-002 | 60-0649-56 |
| Collins ILS-720 ILS | 622-9738-420 | 60-0649-57 |
| Collins ILS-720 ILS | 622-9738-220 | 60-0649-57 |
| Collins ILS-720 ILS | 622-9738-041 | 60-0649-57 |
| Collins ILS-720 ILS | 622-9738-040 | 60-0649-57 |
| Collins ILS-720 ILS | 622-9738-021 | 60-0649-57 |
| Collins ILS-720 ILS | 622-9738-020 | 60-0649-57 |
| Collins VHF-700/A VHF Comm | 822-0693-001 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 822-0693-003 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 822-0693-002 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 622-5219-003 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 622-5219-120 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 622-5219-020 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 622-5219-002 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 622-5219-001 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 822-0693-004 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 622-5219-004 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 822-0693-120 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 822-0693-020 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 622-5219-005 | 60-0649-58 |
| Collins VHF-700/A VHF Comm | 822-0693-005 | 60-0649-58 |
| Collins VHF-700B VHF Comm | 822-1044-121 | 60-0649-59 |
| Collins VHF-700B VHF Comm | 822-1044-020 | 60-0649-59 |
| Collins VHF-700B VHF Comm | 822-1044-004 | 60-0649-59 |

| LRU Name | LRU Part Number | TPS P/N |
|--------------------------------|------------------------|----------------|
| Collins VHF-700B VHF Comm | 822-1044-005 | 60-0649-59 |
| Collins VHF-700B VHF Comm | 822-1044-003 | 60-0649-59 |
| Collins VHF-700B VHF Comm | 822-1044-120 | 60-0649-59 |
| Collins DME-700 DME | 622-4540-001 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-020 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-021 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-023 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-121 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-122 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-022 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-002 | 60-0649-61 |
| Collins DME-700 DME | 622-4540-120 | 60-0649-61 |
| Collins FCC-702 FCC | 622-8757-106 | 60-0649-62 |
| Collins FCC-702 FCC | 622-8757-104 | 60-0649-62 |
| Collins FCC-702 FCC | 622-8757-105 | 60-0649-62 |
| Collins HFS-700 HF Comm | 622-5272-020 | 60-0649-63 |
| Collins HFS-700 HF Comm | 622-5272-023 | 60-0649-63 |
| Collins HFS-700 HF Comm | 622-5272-120 | 60-0649-63 |
| Collins HFS-700 HF Comm | 622-5272-003 | 60-0649-63 |
| Collins HFS-700 HF Comm | 622-5272-001 | 60-0649-63 |
| Collins ADF-900 ADF Rcvr | 822-0299-021 | 60-0649-65 |
| Collins ADF-900 ADF Rcvr | 822-0299-020 | 60-0649-65 |
| Collins ADF-900 ADF Rcvr | 822-0299-220 | 60-0649-65 |
| Collins ADF-900 ADF Rcvr | 822-0299-001 | 60-0649-65 |
| Collins TPR-720/TPR-900 Mode-S | 822-0336-220 | 60-0649-67 |
| Collins TPR-720/TPR-900 Mode-S | 822-0336-020 | 60-0649-67 |
| Collins TPR-720/TPR-900 Mode-S | 822-0336-001 | 60-0649-67 |
| Collins TPR-720/TPR-900 Mode-S | 622-7878-301 | 60-0649-67 |
| Collins TPR-720/TPR-900 Mode-S | 622-7878-201 | 60-0649-67 |
| Collins TPR-720/TPR-900 Mode-S | 622-7878-200 | 60-0649-67 |
| Collins LRA-700 Radio Alt | 622-4542-421 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-101 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-221 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-020 | 60-0649-68 |

| LRU Name | LRU Part Number | TPS P/N |
|-------------------------------|------------------------|----------------|
| Collins LRA-700 Radio Alt | 622-4542-222 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-104 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-420 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-121 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-102 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-120 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-002 | 60-0649-68 |
| Collins LRA-700 Radio Alt | 622-4542-103 | 60-0649-68 |
| Collins ILS-900 ILS | 822-0298-001 | 60-0649-69 |
| Collins ILS-900 ILS | 822-0298-220 | 60-0649-69 |
| Collins ILS-900 ILS | 822-0298-020 | 60-0649-69 |
| Collins RMI-733 Radio Mag Ind | 622-5002-205 | 60-0649-71 |
| Collins RMI-733 Radio Mag Ind | 622-5002-207 | 60-0649-71 |
| Collins RMI-733 Radio Mag Ind | 622-5002-203 | 60-0649-71 |
| Collins VOR-900 VOR | 822-0297-001 | 60-0649-73 |
| Collins VOR-900 VOR | 822-0297-020 | 60-0649-73 |
| Collins VOR-900 VOR | 822-0297-220 | 60-0649-73 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-003 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-012 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3255-009 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-001 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-008 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-004 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0760-009 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-006 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-101 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-001 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-005 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-004 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0761-003 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3255-002 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0760-002 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0760-001 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-005 | 60-0649-76 |

| LRU Name | LRU Part Number | TPS P/N |
|---------------------------------|------------------------|----------------|
| Collins 51RV-4/5 VOR/ILS | 622-3255-001 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-012 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-101 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-008 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0762-005 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3259-005 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 622-3257-006 | 60-0649-76 |
| Collins 51RV-4/5 VOR/ILS | 822-0762-002 | 60-0649-76 |
| Collins GLU-920 MMR | 822-1152-220 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-003 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-122 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-131 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-002 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-120 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-130 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-001 | 60-0649-77 |
| Collins GLU-920 MMR | 822-1152-121 | 60-0649-77 |
| Collins DCP-7000 Control Panel | 622-8590-101 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-108 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-102 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-104 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-112 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-111 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-100 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-109 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-107 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-106 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-105 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-113 | 60-0649-79 |
| Collins DCP-7000 Control Panel | 622-8590-110 | 60-0649-79 |
| Collins DSP-7000 Switch Panel | 622-8591-100 | 60-0649-80 |
| Collins LRA-900 Radio Altimeter | 822-0334-002 | 60-0649-81 |
| Collins LRA-900 Radio Altimeter | 822-0334-020 | 60-0649-81 |
| Collins LRA-900 Radio Altimeter | 822-0334-220 | 60-0649-81 |

| LRU Name | LRU Part Number | TPS P/N |
|---------------------------------|------------------------|----------------|
| Collins LRA-900 Radio Altimeter | 822-0334-221 | 60-0649-81 |
| Collins HFS-900 HF Comm | 822-0330-020 | 60-0649-85 |
| Collins HFS-900 HF Comm | 822-0330-001 | 60-0649-85 |
| Collins HFS-900 HF Comm | 822-0330-220 | 60-0649-85 |
| Collins RDMI-743 RMI | 622-5001-111 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-114 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-110 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-108 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-106 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-109 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-113 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-107 | 60-0649-87 |
| Collins RDMI-743 RMI | 622-5001-104 | 60-0649-87 |
| Collins GNLU-930 MMR | 822-1236-001 | 60-0649-88 |
| Collins TPR-901 Mode-S | 822-1338-001 | 60-0649-89 |
| Collins TPR-901 Mode-S | 822-1338-002 | 60-0649-89 |
| Collins TPR-901 Mode-S | 822-1338-003 | 60-0649-89 |
| Collins TPR-901 Mode-S | 822-1338-021 | 60-0649-89 |
| Collins TPR-901 Mode-S | 822-1338-020 | 60-0649-89 |
| Collins TTR-921 TCAS | 822-1293-002 | 60-0649-90 |
| Collins TTR-921 TCAS | 822-1293-320 | 60-0649-90 |
| Collins TTR-921 TCAS | 822-1293-321 | 60-0649-90 |
| Collins TTR-921 TCAS | 822-1293-220 | 60-0649-90 |
| Collins TTR-921 TCAS | 822-1293-001 | 60-0649-90 |
| Collins HFS-900D HF Comm | 822-0990-020 | 60-0649-92 |
| Collins HFS-900D HF Comm | 822-0990-003 | 60-0649-92 |
| Collins HFS-900D HF Comm | 822-0990-001 | 60-0649-92 |
| Collins HFS-900D HF Comm | 822-0990-002 | 60-0649-92 |
| Collins HFS-900D HF Comm | 822-0990-004 | 60-0649-92 |
| Collins 628T-2/A HF Comm | 622-5377-001 | 60-0649-93 |
| Collins 628T-2/A HF Comm | 622-3372-001 | 60-0649-93 |
| Collins TTR-92x P/N Utility | 622-8971-022 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-020 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-122 | 60-0649-94 |

| LRU Name | LRU Part Number | TPS P/N |
|-----------------------------|------------------------|----------------|
| Collins TTR-92x P/N Utility | 622-8971-420 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-320 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-322 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-500 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-622 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-120 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-620 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-422 | 60-0649-94 |
| Collins TTR-92x P/N Utility | 622-8971-522 | 60-0649-94 |
| Collins MCP-770 MCP | 822-0195-102 | 60-0649-95 |
| Collins MCP-770 MCP | 822-0195-100 | 60-0649-95 |
| Collins 51RV-1 VOR | 522-2450-115 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-016 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-000 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-011 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-120 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-015 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-020 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-114 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-014 | 60-0653-21 |
| Collins 51RV-1 VOR | 522-2450-111 | 60-0653-21 |
| Collins 51RV-2B VOR | 522-4280-109 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-008 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-108 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-107 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-105 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-102 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4977-001 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-101 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-001 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-007 | 60-0653-22 |
| Collins 51RV-2B VOR | 777-1480-001 | 60-0653-22 |
| Collins 51RV-2B VOR | 522-4280-005 | 60-0653-22 |
| Collins 621A-3 ATC | 522-2703-000 | 60-0653-25 |

| LRU Name | LRU Part Number | TPS P/N |
|----------------------------|------------------------|----------------|
| Collins 621A-3 ATC | 522-2703-013 | 60-0653-25 |
| Collins 621A-3 ATC | 522-2703-012 | 60-0653-25 |
| Collins 621A-3 ATC | 522-2703-011 | 60-0653-25 |
| Collins 621A-6/6A ATC | 622-2224-003 | 60-0653-26 |
| Collins 621A-6/6A ATC | 622-2224-101 | 60-0653-26 |
| Collins 621A-6/6A ATC | 622-2224-002 | 60-0653-26 |
| Collins 621A-6/6A ATC | 622-2224-001 | 60-0653-26 |
| Collins 621A-6/6A ATC | 787-6211-003 | 60-0653-26 |
| Collins 621A-6/6A ATC | 787-6211-002 | 60-0653-26 |
| Collins 621A-6/6A ATC | 787-6211-001 | 60-0653-26 |
| Collins 621A-6/6A ATC | 622-2224-201 | 60-0653-26 |
| Collins 860E-5 DME | 622-2921-002 | 60-0653-27 |
| Collins 860E-5 DME | 622-2921-001 | 60-0653-27 |
| Collins 860E-5 DME | 622-2921-005 | 60-0653-27 |
| Collins 860E-5 DME | 622-2921-006 | 60-0653-27 |
| Collins 860E-5 DME | 622-2921-004 | 60-0653-27 |
| Collins 618M-5/5A VHF Comm | 822-1045-508 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-509 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-001 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-311 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-011 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-411 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-206 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-101 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-103 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-203 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-205 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-506 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-209 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-003 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-111 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-009 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-001 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-003 | 60-0653-34 |

| LRU Name | LRU Part Number | TPS P/N |
|----------------------------|------------------------|----------------|
| Collins 618M-5/5A VHF Comm | 822-1045-004 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-005 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-008 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-301 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-303 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-401 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-403 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-006 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-503 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1046-208 | 60-0653-34 |
| Collins 618M-5/5A VHF Comm | 822-1045-505 | 60-0653-34 |
| Collins 51Y-7/A/C ADF | 792-6216-003 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 622-3178-001 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 792-6216-001 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 777-1492-006 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 777-1492-005 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 777-1492-003 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 777-1492-002 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 792-6216-004 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 622-3178-005 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 622-3178-003 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 622-3178-002 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 792-6216-002 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 777-1492-004 | 60-0653-36 |
| Collins 51Y-7/A/C ADF | 777-1492-001 | 60-0653-36 |
| Collins VHF-900 Alignment | 822-1047-030 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-1047-003 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-1047-020 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-0323-002 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-0323-020 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-0323-220 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-1047-010 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-1047-002 | 60-0717-08 |
| Collins VHF-900 Alignment | 822-1047-220 | 60-0717-08 |

| LRU Name | LRU Part Number | TPS P/N |
|----------------------------|------------------------|----------------|
| Collins 860E-4 DME | 622-2920-001 | 60-0653-38 |
| Collins 860E-4 DME | 622-2920-003 | 60-0653-38 |
| Collins 860E-4 DME | 622-2920-005 | 60-0653-38 |
| Collins 860E-4 DME | 622-2920-002 | 60-0653-38 |
| Collins 860E-4 DME | 622-2920-004 | 60-0653-38 |
| Collins TPR-710A ATC | 622-5446-102 | 60-0717-03 |
| Collins TPR-710A ATC | 622-5446-001 | 60-0717-03 |
| Collins TPR-710A ATC | 622-5446-002 | 60-0717-03 |
| Collins TPR-710A ATC | 622-5446-001 | 60-0653-39 |
| Collins TPR-710A ATC | 622-5446-002 | 60-0653-39 |
| Collins TPR-710A ATC | 622-5446-101 | 60-0653-39 |
| Collins TPR-710A ATC | 622-5446-102 | 60-0653-39 |
| Collins TPR-710A ATC | 622-5446-101 | 60-0717-03 |
| Collins 618M-3/3A VHF Comm | 622-1181-003 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1181-006 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-010 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-203 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-102 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-011 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-208 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-003 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1181-001 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1181-008 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-205 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1181-005 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1181-004 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1181-009 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1181-002 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-101 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-206 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-001 | 60-0653-40 |
| Collins 618M-3/3A VHF Comm | 622-1396-002 | 60-0653-40 |
| Collins 51Y-4/4A ADF Rcvr | 522-2587-013 | 60-0653-42 |
| Collins 51Y-4/4A ADF Rcvr | 522-2587-000 | 60-0653-42 |

| LRU Name | LRU Part Number | TPS P/N |
|--------------------------------|------------------------|----------------|
| Collins 51Y-4/4A ADF Rcvr | 522-1836-013 | 60-0653-42 |
| Collins 51Y-4/4A ADF Rcvr | 522-1836-000 | 60-0653-42 |
| Collins 51Y-4/4A ADF Rcvr | 522-2587-015 | 60-0653-42 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-018 | 60-0653-43 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-017 | 60-0653-43 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-000 | 60-0653-43 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-011 | 60-0653-43 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-013 | 60-0653-43 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-014 | 60-0653-43 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-015 | 60-0653-43 |
| Collins 51Z-4 Mkr Rcvr | 522-2996-016 | 60-0653-43 |
| Collins 618M-2B/2D VHF Comm | 522-4088-004 | 60-0653-45 |
| Collins 618M-2B/2D VHF Comm | 522-4088-001 | 60-0653-45 |
| Collins 618M-2B/2D VHF Comm | 522-4088-203 | 60-0653-45 |
| Collins 618M-2B/2D VHF Comm | 522-4089-204 | 60-0653-45 |
| Collins 618M-2B/2D VHF Comm | 522-4089-005 | 60-0653-45 |
| Collins 618M-2B/2D VHF Comm | 522-4089-004 | 60-0653-45 |
| Collins 618M-2B/2D VHF Comm | 522-4088-204 | 60-0653-45 |
| Collins 618T-2/5 HF Comm | 522-1501-000 | 60-0653-46 |
| Collins 618T-2/5 HF Comm | 622-2588-001 | 60-0653-46 |
| Collins 618T-2/5 HF Comm | 522-1501-044 | 60-0653-46 |
| Collins 618T-2/5 HF Comm | 522-1501-041 | 60-0653-46 |
| Collins 618T-2/5 HF Comm | 522-1501-043 | 60-0653-46 |
| Collins 618T-2/5 HF Comm | 622-2588-002 | 60-0653-46 |
| Collins 628T-1 HF Comm | 622-3371-004 | 60-0653-48 |
| Collins 628T-1 HF Comm | 622-3371-001 | 60-0653-48 |
| Collins 860F-4 Radio Altimeter | 622-3890-003 | 60-0653-57 |
| Collins 860F-4 Radio Altimeter | 622-3890-004 | 60-0653-57 |
| Collins 860F-4 Radio Altimeter | 622-3890-015 | 60-0653-57 |
| Collins 860F-4 Radio Altimeter | 622-3890-002 | 60-0653-57 |
| Collins 860F-4 Radio Altimeter | 622-3890-014 | 60-0653-57 |
| Collins 860F-1 Radio Altimeter | 522-3698-003 | 60-0653-60 |
| Collins 860F-1 Radio Altimeter | 522-3698-004 | 60-0653-60 |
| Collins 860F-1 Radio Altimeter | 522-3698-006 | 60-0653-60 |

| LRU Name | LRU Part Number | TPS P/N |
|---------------------------------------|------------------------|----------------|
| Collins 860F-1 Radio Altimeter | 522-3698-011 | 60-0653-60 |
| Collins 860F-1 Radio Altimeter | 522-3698-002 | 60-0653-60 |
| Collins 860F-1 Radio Altimeter | 522-3698-013 | 60-0653-60 |
| Collins 860F-1 Radio Altimeter | 522-3698-014 | 60-0653-60 |
| Collins 346D-2B PA Amp | 622-4096-002 | 60-0653-61 |
| Collins 346D-2B PA Amp | 622-4096-001 | 60-0653-61 |
| Collins ILS-70 ILS | 792-6021-004 | 60-0653-65 |
| Collins ILS-70 ILS | 792-6021-102 | 60-0653-65 |
| Collins ILS-70 ILS | 792-6021-002 | 60-0653-65 |
| Collins ILS-70 ILS | 792-6021-103 | 60-0653-65 |
| Collins ILS-70 ILS | 792-6021-104 | 60-0653-65 |
| Collins ILS-70 ILS | 792-6021-003 | 60-0653-65 |
| Teledyne 2233000 DFDAU | 2233000-4 | 60-0649-23 |
| Teledyne 2233000 DFDAU | 2233000-3 | 60-0649-23 |
| Teledyne 2233000 DFDAU | 2233000-1A | 60-0649-23 |
| Teledyne 2233000 DFDAU | 2233000-3A | 60-0649-23 |
| Teledyne 2233000 DFDAU | 2233000-1 | 60-0649-23 |
| Teledyne 2233000 DFDAU | 2233000-4A | 60-0649-23 |
| Boeing Audio Accessory Unit | 285T0001-69 | 60-0649-41 |
| Boeing Digital Stall Warning Computer | 65-52819-7 | 60-0653-17 |
| Boeing Digital Stall Warning Computer | 65-52819-13 | 60-0653-17 |
| Boeing Digital Stall Warning Computer | 65-52819-23 | 60-0653-17 |
| Boeing Digital Stall Warning Computer | 65-52819-25 | 60-0653-17 |
| Boeing Autoslat Computer | 65-52818-14 | 60-0653-19 |
| Boeing Autoslat Computer | 65-52818-5 | 60-0653-19 |
| Boeing Autoslat Computer | 65-52818-9 | 60-0653-19 |
| Boeing Autoslat Computer | 65-52818-7 | 60-0653-19 |
| Thales ERT-530A Radio Alt | 9599-607-14931 | 60-0649-42 |
| Thales TLS-755 MMR | TLS755-01-0100A | 60-0649-43 |
| Thales TLS-755 MMR | TLS755-01-0101B | 60-0649-43 |
| Thales TLS-755 MMR | TLS755-01-0102A | 60-0649-43 |
| Thales ERT-530 Radio Alt | 9599-607-14943 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14921 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14941 | 60-0717-06 |

| LRU Name | LRU Part Number | TPS P/N |
|--------------------------|------------------------|----------------|
| Thales ERT-530 Radio Alt | 9599-607-14940 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14923 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14901 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14905 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14939 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14919 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14942 | 60-0717-06 |
| Thales ERT-530 Radio Alt | 9599-607-14932 | 60-0717-06 |
| ACSS XS-950 Mode-S | 7517800-10003 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-10004 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-55001 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-55002 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-11006 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-55003 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-55004 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-55005 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-10001 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-56006 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-10100 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-10007 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-10005 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-56009 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-55009 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-11009 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-10009 | 60-0649-74 |
| ACSS XS-950 Mode-S | 7517800-10002 | 60-0649-74 |
| ACSS RT-950 TCAS | 7517900-10004 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-71012 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10001 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10010 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55009 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517905-61002 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10006 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55006 | 60-0649-75 |

| LRU Name | LRU Part Number | TPS P/N |
|----------------------|------------------------|----------------|
| ACSS RT-950 TCAS | 7517900-71006 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-71007 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-71002 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10002 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-71011 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55002 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10007 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10011 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10012 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-71004 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-71003 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-10003 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55011 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55001 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55003 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55004 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55007 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-71010 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55010 | 60-0649-75 |
| ACSS RT-950 TCAS | 7517900-55012 | 60-0649-75 |
| ACSS VSI/TRA Display | 4067241-844 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-893 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-802 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-894 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-864 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-801 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-892 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-891 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-860 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-861 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-803 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-863 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-804 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-865 | 60-0649-86 |

| LRU Name | LRU Part Number | TPS P/N |
|--------------------------------------|------------------------|----------------|
| ACSS VSI/TRA Display | 4067241-880 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-843 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-881 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-840 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-806 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-841 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-890 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-842 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-845 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-895 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-862 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-885 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-884 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-883 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-882 | 60-0649-86 |
| ACSS VSI/TRA Display | 4067241-805 | 60-0649-86 |
| ACSS 4066010-90x TCAS | 4066010-904 | 60-0653-52 |
| ACSS 4066010-90x TCAS | 4066010-905 | 60-0653-52 |
| ACSS 4066010-90x TCAS | 4066010-907 | 60-0653-52 |
| ACSS 4061400-90x Mode-S | 4061400-903 | 60-0653-62 |
| ACSS 4061400-90x Mode-S | 4061400-904 | 60-0653-62 |
| ACSS 4061400-90x Mode-S | 4061400-905 | 60-0653-62 |
| Crane Skid Control Unit | 42-719-01 | 60-0717-00 |
| Crane Skid Control Unit | 42-719-02 | 60-0717-00 |
| Honeywell HG2001BC IRU (Automatic) | HG2001BC02 | 60-1200-32 |
| Honeywell HG2001BC IRU (Automatic) | HG2001BC03 | 60-1200-32 |
| Honeywell HG1103BA IRU (Automatic) | HG1103BA | 60-1200-35 |
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC04 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC01 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC03 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC05 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC06 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC07 | 60-1200-38 |
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC50 | 60-1200-38 |

| LRU Name | LRU Part Number | TPS P/N |
|--------------------------------------|------------------------|----------------|
| Honeywell HG2050AC ADIRU (Automatic) | HG2050AC02 | 60-1200-38 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD10 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD07 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD11 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AC03 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AC09 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AC10 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AC11 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD05 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD12 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AE09 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD04 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AE11 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD06 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AD09 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AC04 | 60-1200-09 |
| Honeywell HG1050AX IRU (Automatic) | HG1050AE10 | 60-1200-09 |
| Honeywell HG1150BD IRU (Automatic) | HG1150BD02 | 60-1200-11 |
| Honeywell HG1150AC ADIRU (Automatic) | HG1150AC07 | 60-1200-13 |
| Honeywell HG1150AC ADIRU (Automatic) | HG1150AC06 | 60-1200-13 |
| Honeywell HG1150AC ADIRU (Automatic) | HG1150AC08 | 60-1200-13 |
| Honeywell HG1150AC ADIRU (Automatic) | HG1150AC05 | 60-1200-13 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AD10 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AD12 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AC08 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AC09 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AC13 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AE21 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AC06 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AE22 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AE20 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AD09 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AD11 | 60-1200-22 |
| Honeywell HG2030 ADIRU (Automatic) | HG2030AE23 | 60-1200-22 |

| LRU Name | LRU Part Number | TPS P/N |
|---|------------------------|----------------|
| Honeywell HG2030 ADIRU (Automatic) | HG2030AC11 | 60-1200-22 |
| Honeywell HG1050BD02/05 IRU (Automatic) | HG1050BD05 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Automatic) | HG1050BD09 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Automatic) | HG1050BD08 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Automatic) | HG1050BD07 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Automatic) | HG1050BD06 | 60-1200-23 |
| Honeywell HG1050BD02/05 IRU (Automatic) | HG1050BD02 | 60-1200-23 |

IRS 1200 TPS Status Report



TPS Number: TP-0001-01

TP Program #: 60-1200-35 Version: 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG1103BA IRU (Semi-Auto) | 1/25/2006 | ATLAS | 26007198-104 | | C | 5/2/1995 | | |
| Honeywell | HG1103BA IRU (Automatic) | 1/25/2006 | ATLAS | 26007198-104 | | C | 5/2/1995 | | |
| Honeywell | HG1103BA IRU (Semi-Auto) | 1/25/2006 | ATA | 34-21-30A | | 4 | 7/1/2005 | | |
| Honeywell | HG1103BA IRU (Automatic) | 1/25/2006 | ATA | 34-21-30A | | 4 | 7/1/2005 | | |

TPS Number: TP-0001-02

TP Program #: 60-1200-35 Version: 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG1103BA IRU (Semi-Auto) | 1/25/2006 | ATLAS | 26007198-104 | | C | 5/2/1995 | | |
| Honeywell | HG1103BA IRU (Automatic) | 1/25/2006 | ATLAS | 26007198-104 | | C | 5/2/1995 | | |
| Honeywell | HG1103BA IRU (Semi-Auto) | 1/25/2006 | ATA | 34-21-30A | | 4 | 7/1/2005 | | |
| Honeywell | HG1103BA IRU (Automatic) | 1/25/2006 | ATA | 34-21-30A | | 4 | 7/1/2005 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0007-01

TP Program #: 60-1200-23 Version: 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|---------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG1050BD02/05 IRU (Semi-A | 3/7/2008 | ATLAS | 26008370-208 | | | 1/1/2007 | | |
| Honeywell | HG1050BD02/05 IRU (Automa | 3/7/2008 | ATLAS | 26008370-208 | | | 1/1/2007 | | |

TPS Number: TP-0007-02

TP Program #: 60-1200-23 Version: 1.6

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|---------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG1050BD02/05 IRU (Semi-A | 3/7/2008 | ATLAS | 26008370-208 | | | 1/1/2007 | | |
| Honeywell | HG1050BD02/05 IRU (Automa | 3/7/2008 | ATLAS | 26008370-208 | | | 1/1/2007 | | |

TPS Number: TP-0008-01

TP Program #: 60-1200-26 Version: 1.3

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | CG1137AC MSU | 11/17/2008 | ATA | 34-21-17 | | 5 | 6/15/2005 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0011-01

TP Program #: 60-1200-34 **Version:** 2.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | CG1135AC ISDU | 11/20/2008 | ATLAS | 26008368-207 | | | | | |
| Honeywell | CG1135AC ISDU | 11/20/2008 | ATA | 34-21-11A | | 5 | 3/1/2003 | | |

TPS Number: TP-0016-01

TP Program #: 60-1200-22 **Version:** 2.9

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|--------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG2030 ADIRU (Semi-Auto) | 4/9/2012 | ATLAS | 26013137-213 | | 0 | 3/1/2007 | | |
| Honeywell | HG2030 ADIRU (Automatic) | 4/9/2012 | ATLAS | 26013137-213 | | 0 | 3/1/2007 | | |
| Honeywell | HG2030 ADIRU (Automatic) | 4/9/2012 | ATA | 34-27-22 | | 6 | 8/15/2007 | | |
| Honeywell | HG2030 ADIRU (Semi-Auto) | 4/9/2012 | ATA | 34-27-22 | | 6 | 8/15/2007 | | |
| Honeywell | HG2030 ADIRU (Automatic) | 4/9/2012 | ATA | M45-3346-2000 | | 0 | 8/20/2007 | | |
| Honeywell | HG2030 ADIRU (Semi-Auto) | 4/9/2012 | ATA | M45-3346-2000 | | 0 | 8/20/2007 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0016-02

TP Program #: 60-1200-22

Version: 2.9

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|--------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG2030 ADIRU (Semi-Auto) | 4/9/2012 | ATLAS | 26013137-213 | | 0 | 3/1/2007 | | |
| Honeywell | HG2030 ADIRU (Automatic) | 4/9/2012 | ATLAS | 26013137-213 | | 0 | 3/1/2007 | | |
| Honeywell | HG2030 ADIRU (Automatic) | 4/9/2012 | ATA | 34-27-22 | | 6 | 8/15/2007 | | |
| Honeywell | HG2030 ADIRU (Semi-Auto) | 4/9/2012 | ATA | 34-27-22 | | 6 | 8/15/2007 | | |
| Honeywell | HG2030 ADIRU (Semi-Auto) | 4/9/2012 | ATA | M45-3346-2000 | | 0 | 8/20/2007 | | |
| Honeywell | HG2030 ADIRU (Automatic) | 4/9/2012 | ATA | M45-3346-2000 | | 0 | 8/20/2007 | | |

TPS Number: TP-0016-04

TP Program #: 60-1200-41

Version: 2.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|---------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG2030 Level II GPS/ADIRU | 5/27/2008 | ATLAS | 26013137-213 | | | 3/1/2007 | | |
| Honeywell | HG2030 Level II GPS/ADIRU | 5/27/2008 | ATA | 34-27-22 | | 6 | 8/15/2007 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0017-00

TP Program #: 60-1200-17 Version: 2.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|----------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG2060 FTADIRU | 10/19/2007 | ATLAS | 26019465-101 | | | | | |
| Honeywell | HG2060 FTADIRU | 10/19/2007 | ATA | 34-26-42A | | 4 | 5/15/2004 | | |

TPS Number: TP-0018-00

TP Program #: 60-1200-15 Version: 2.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG2040 SAARU | 10/22/2007 | ATLAS | 26018622-102 | | | | | |
| Honeywell | HG2040 SAARU | 10/22/2007 | ATA | 34-26-41A | | 4 | 2/15/2002 | | |

TPS Number: TP-0018-01

TP Program #: 60-1200-28 Version: 1.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-----------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG2040 Level II SAARU | 7/23/2002 | ATLAS | 26018622-101 | | | | | |
| Honeywell | HG2040 Level II SAARU | 7/23/2002 | ATA | 34-26-41A | | 4 | 2/15/2002 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0019-01

TP Program #: 60-1200-40 **Version: 2.0**

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | CG1092AC IRMP | 11/21/2003 | ATLAS | 26005322-207 | | | 11/1/2002 | | |
| Honeywell | CG1092AC IRMP | 11/21/2003 | ATA | 34-21-06A | | 3 | 3/1/2003 | | |

TPS Number: TP-0020-00

TP Program #: 60-1200-09 **Version: 5.1**

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|--------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG1050AX IRU (Automatic) | 9/5/2018 | ATLAS | 26005584-214 | | | | | |
| Honeywell | HG1050AX IRU (Semi-Auto) | 9/5/2018 | ATLAS | 26005584-214 | | | | | |
| Honeywell | HG1050AX IRU (Automatic) | 9/5/2018 | ATA | 34-27-20B | | 5 | 5/1/2012 | | |
| Honeywell | HG1050AX IRU (Semi-Auto) | 9/5/2018 | ATA | 34-27-20B | | 5 | 5/1/2012 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0020-02

TP Program #: 60-1200-09 **Version: 5.1**

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|--------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG1050AX IRU (Automatic) | 9/5/2018 | ATLAS | 26005584-214 | | | | | |
| Honeywell | HG1050AX IRU (Semi-Auto) | 9/5/2018 | ATLAS | 26005584-214 | | | | | |
| Honeywell | HG1050AX IRU (Automatic) | 9/5/2018 | ATA | 34-27-20B | | 5 | 5/1/2012 | | |
| Honeywell | HG1050AX IRU (Semi-Auto) | 9/5/2018 | ATA | 34-27-20B | | 5 | 5/1/2012 | | |

TPS Number: TP-0021-00

TP Program #: 60-1200-13 **Version: 3.6**

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|----------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG1150AC ADIRU (Semi-Auto) | 5/29/2009 | ATLAS | 26005583-214 | | | 7/1/2007 | | |
| Honeywell | HG1150AC ADIRU (Automatic) | 5/29/2009 | ATLAS | 26005583-214 | | | 7/1/2007 | | |
| Honeywell | HG1150AC ADIRU (Semi-Auto) | 5/29/2009 | ATA | 34-12-34 | | 8 | 8/15/2007 | | |
| Honeywell | HG1150AC ADIRU (Automatic) | 5/29/2009 | ATA | 34-12-34 | | 8 | 8/15/2007 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0021-02

TP Program #: 60-1200-13 **Version: 3.6**

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|----------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG1150AC ADIRU (Automatic) | 5/29/2009 | ATLAS | 26005583-214 | | | 7/1/2007 | | |
| Honeywell | HG1150AC ADIRU (Semi-Auto) | 5/29/2009 | ATLAS | 26005583-214 | | | 7/1/2007 | | |
| Honeywell | HG1150AC ADIRU (Semi-Auto) | 5/29/2009 | ATA | 34-12-34 | | 8 | 8/15/2007 | | |
| Honeywell | HG1150AC ADIRU (Automatic) | 5/29/2009 | ATA | 34-12-34 | | 8 | 8/15/2007 | | |

TPS Number: TP-0022-00

TP Program #: 60-1200-11 **Version: 2.2**

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|--------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG1150BD IRU (Automatic) | 7/20/2007 | ATLAS | 26005591-210 | | | | | |
| Honeywell | HG1150BD IRU (Semi-Auto) | 7/20/2007 | ATLAS | 26005591-210 | | | | | |
| Honeywell | HG1150BD IRU (Automatic) | 7/20/2007 | ATA | 34-21-32A | | 3 | 12/1/1999 | | |
| Honeywell | HG1150BD IRU (Semi-Auto) | 7/20/2007 | ATA | 34-21-32A | | 3 | 12/1/1999 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0022-02

TP Program #: 60-1200-11 Version: 2.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG1150BD IRU (Semi-Auto) | 9/9/2008 | ATLAS | 26005591-210 | | | | | |
| Honeywell | HG1150BD IRU (Automatic) | 9/9/2008 | ATLAS | 26005591-210 | | | | | |
| Honeywell | HG1150BD IRU (Semi-Auto) | 9/9/2008 | ATA | 34-21-32A | | 3 | 12/1/1999 | | |
| Honeywell | HG1150BD IRU (Automatic) | 9/9/2008 | ATA | 34-21-32A | | 3 | 12/1/1999 | | |

TPS Number: TP-0023-00

TP Program #: 60-1200-18 Version: 2.0

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|-------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | CG1093 IRMP | 10/19/2004 | ATLAS | 26005322-207 | | | 5/21/2002 | | |
| Honeywell | CG1093 IRMP | 10/19/2004 | ATA | 34-21-08 | | | | | |
| Honeywell | CG1093 IRMP | 10/19/2004 | ATA | 34-21-21 | | | | | |

TPS Number: TP-0024-00

TP Program #: 60-1200-19 Version: 1.22

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | CG1234AC MSU | 10/19/2000 | ATA | 34-21-27 | | 2 | 6/30/1999 | 4 | 8/6/2002 |

IRS 1200 TPS Status Report



TPS Number: TP-0025-00

TP Program #: 60-1200-20 Version: 3.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | CG1151AC CDU | 6/3/2009 | ATLAS | 26005585-207 | | | 7/1/2005 | | |
| Honeywell | CG1151AC CDU | 6/3/2009 | ATA | 34-12-12 | | 2 | 8/15/2005 | | |

TPS Number: TP-0027-01

TP Program #: 60-1200-32 Version: 1.5

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG2001BC IRU (Semi-Auto) | 10/8/2008 | ATLAS | 26005587-206 | | | | | |
| Honeywell | HG2001BC IRU (Automatic) | 10/8/2008 | ATLAS | 26005587-206 | | | | | |

TPS Number: TP-0027-02

TP Program #: 60-1200-32 Version: 1.5

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG2001BC IRU (Semi-Auto) | 10/8/2008 | ATLAS | 26005587-206 | | | | | |
| Honeywell | HG2001BC IRU (Automatic) | 10/8/2008 | ATLAS | 26005587-206 | | | | | |

IRS 1200 TPS Status Report



TPS Number: TP-0029-00

TP Program #: 60-1200-25 Version: 2.5

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|---------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | CG1136AC ISDU | 11/21/2008 | ATLAS | 26008369-207 | | | 10/1/2002 | | |
| Honeywell | CG1136AC ISDU | 11/21/2008 | ATA | 34-21-14A | | 4 | 3/1/2003 | | |

TPS Number: TP-0031-01

TP Program #: 60-1200-30 Version: 1.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|-------------|------|------|-----------|-----|----------|
| Honeywell | CG1237BD MSU | 7/27/2007 | ATA | 34-21-33 | | 4 | 6/1/2006 | | |

TPS Number: TP-0032-01

TP Program #: 60-1200-31 Version: 1.1

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|--------------|-------------|-------|-------------|------|------|-----------|-----|-----------|
| Honeywell | CG1244AD MSU | 5/27/2005 | ATA | 34-26-46 | | 2 | | 3 | 6/30/1999 |

IRS 1200 TPS Status Report



TPS Number: TP-0033-01

TP Program #: 60-1200-38 Version: 1.4

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|----------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG2050AC ADIRU (Semi-Auto | 10/10/2002 | ATLAS | 26018907-101 | | | | | |
| Honeywell | HG2050AC ADIRU (Automatic) | 10/10/2002 | ATLAS | 26018907-101 | | | | | |
| Honeywell | HG2050AC ADIRU (Semi-Auto | 10/10/2002 | ATA | 34-26-93 | | 4 | | | |
| Honeywell | HG2050AC ADIRU (Automatic) | 10/10/2002 | ATA | 34-26-93 | | 4 | | | |
| Honeywell | HG2050AC ADIRU (Semi-Auto | 10/10/2002 | ATA | 34-27-28A | | 1 | 2/15/2004 | | |
| Honeywell | HG2050AC ADIRU (Automatic) | 10/10/2002 | ATA | 34-27-28A | | 1 | 2/15/2004 | | |

TPS Number: TP-0033-02

TP Program #: 60-1200-38 Version: 1.5

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------|----------------------------|-------------|-------|--------------|------|------|-----------|-----|----------|
| Honeywell | HG2050AC ADIRU (Semi-Auto | 5/22/2013 | ATLAS | 26018907-101 | | | | | |
| Honeywell | HG2050AC ADIRU (Automatic) | 5/22/2013 | ATLAS | 26018907-101 | | | | | |
| Honeywell | HG2050AC ADIRU (Automatic) | 5/22/2013 | ATA | 34-26-93 | | 4 | | | |
| Honeywell | HG2050AC ADIRU (Semi-Auto | 5/22/2013 | ATA | 34-26-93 | | 4 | | | |
| Honeywell | HG2050AC ADIRU (Semi-Auto | 5/22/2013 | ATA | 34-27-28A | | 1 | 2/15/2004 | | |
| Honeywell | HG2050AC ADIRU (Automatic) | 5/22/2013 | ATA | 34-27-28A | | 1 | 2/15/2004 | | |

IRS 1200 TPS Status Report



TPS Number: TP-0033-03

TP Program #: 60-1200-44

Version: 1.2

| LRU OEM: | LRU Name: | TP Revised: | Type: | DOC Number: | Vol: | Rev: | Rev Date: | TR: | TR Date: |
|-----------------|------------------------------|--------------------|--------------|--------------------|-------------|-------------|------------------|------------|-----------------|
| Honeywell | HG2050 Limited Level II ADIR | 2/10/2006 | ATLAS | 26018907-101 | | | | | |
| Honeywell | HG2050 Limited Level II ADIR | 2/10/2006 | ATLAS | 26019170-202 | | | 4/1/2007 | | |